

PRIMARY CORNER DESCRIPTION ¼ COR. OF SEC. 8 & 9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Harvey Gordon & Charles T. Gardner, Deputy Surveyors under contract #52, dated Feb. 17, 1855 - (DCSO records Vol. 4 Page(s) 1620)

-----  
Set post from which,  
A Fir, 12" dia., bears S.8°E., 35 lks.  
A Fir, 20" dia., bears S.23°W., 35 lks.

-----  
Douglas County Surveyors Office - Randall Smith & Stephen Flause - June 17, 1996 - C.S. 64/69-5

-----  
Note: FD. Brass Cap & BT's from an unrecorded 1977 DCSO Renewal.

Mon. Fd.- 2½" Brass cap on a 1½" O.D. iron, protrudes 7" above ground. (1977 DCSO)

DOUGLAS COUNTY SURVEYOR  
T 22 S  
R 9 W  
¼  
S 8 S 9  
1977

1½" I.D. iron pipe 46" long protrudes 28" above ground bears south 1' from DCSO BC/IP. source unknown.

BT's Fd.- 20" now 25" dia. 9' high D.Fir snag showing scribe marks "¼ S BT" bears S.68½°E., 35.6' OBT

10" now root hole with rotted fir roots, bears N.44°W., 16.5'.

25" D.Fir with a fully healed double blaze, bears S.75°W., 25.1'. 1977 DCSO.

8" D.Fir, with a fully healed double blaze, bears N.85°E., 5.4'. 1977 DCSO.

Note: DCSO BT Tag's are dated 10-5-77 a check of field diary on 10-5-77 was made, records indicate that Rod Kimberling and Mike Cline were at corner.

New BT's'- 8" dia. D.Fir, double blazed and scribed "¼ S8 CS BT", bears N.21°W., 32.7'.

9" dia. D.Fir, double blazed and scribed "¼ S9 CS BT", bears S.16½°E., 10.2'.

A new fence corner with fence lines running S.30°W., and S.80°W., bears S.45°W., 11.5'.

-----  
Fd. & used on Dependent resurvey by Boyd W. Peterson & John A. Farmer, Cadastral Surveyors, under Group #1791, surveyed Oct. 1995/Feb. 1998. (DCSO records Vol. 52 Page(s) 19867)