

PRIMARY CORNER DESCRIPTION Sec Cor for 5 & 8 on W bdy S 4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1670)

-----

Set Fir post 4½ ft. long, 4" sq., 24" in the ground, for cor. to secs. 4, 5, 8 and 9, mkd. T22S S4 on the NE.; R9W S9 on the SE.; S8 on the SW.; and S5 on the NW. faces with 5 notches on the S. and 4 notches on the E. edges, from which,

A Fir 10" dia., bears N.53°30'E., 8 lks. dist. mkd. T22S R9W S4 BT.

A Fir 8" dia., bears S.26°30'E., 13 lks. dist. mkd. T22S R9W S9 BT.

A Fir 10" dia., bears S.31°W., 33 lks. dist. mkd. T22S R9W S8 BT.

A Fir 12" dia., bears N.86°W., 29 lks. dist. mkd. T22S R9W S5 BT.

V. W. Hosford - Aug. 1954 - C.S. File 41/292 and M 10-80

-----

I find the corner to secs. 5 & 8. This corner is marked by a 4" Fir post. All original BTs were found, all dead except SE which is a living 10" tree. Scribing has not been destroyed on trees for secs. 4 and 9.

Douglas Co. Surveyors Office - James Byron, Deputy - John Powell and crew - Oct. 18, 1971 - C.S. File 53/66-129

-----


Found - Squared stake, down, near corner.

10" D.Fir, now stump, S.31°W., 21.8 ft. scribe marks visible.

8" D.Fir, now down, S.27½°E., 8.6 ft., scribe visible.

12" D.Fir, now stump, N.86°W., 19.1 ft. scribe visible.

Set Brass cap at cor. mkd: County Surveyors Office



New BTs -6" D.Fir S.69°E., 12.8 ft. scribed S4 CS BT.

6" D.Fir S.86°W., 8.5 ft. scribed S8 CS BT.

6" D.Fir N.61°E., 6.1 ft. scribed S4 CS BT.

BLM resurvey by Joel E. Robb, Cadastral Surveyor, under Group #1281, surveyed Aug/Oct. 1985 - (DCSO records Vol. 48 Page(s) 18191)

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec cor for 5 & 8 on W bdy Sec 4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

The cor. of secs. 5 and 8 only, recovered and recorded by Hosford, in 1954, for the Evans Products Co., and perpetuated and recorded by Powell in 1971, monumented with an iron post 1¼" dia., firmly set, projecting 10" above ground, with 1971 brass cap,

from which the remains of the original bearing trees:

A root hole, bears S.26½°E., 13 lks. dist., with a down Fir, 9" dia., alongside, no marks visible.

A decayed Fir stump 14" dia., bears S.29°W., 33 lks. dist. with scribe marks T22S R9W visible on opened blaze. (Rec. S.31°W)

A decayed Fir stump 14" dia., bears N.88½°W., 29 lks. dist. no marks remaining. (Rec. N.86°W.)

and bearing trees mkd. by Powell:

A Fir 10" dia., bears N.61°E., 9½ lks. dist. with healed blaze.

A Fir 9" dia., bears S.69°E., 19½ lks. dist. with healed blaze.

A Fir 8" dia., bears S.86°W., 13 lks. dist. with healed blaze.

and a new bearing tree:

A Fir 8" dia., bears N.31°W., 35½ lks. dist. mkd. T22S R9W S5 BT.

Fd. & used on Dependent resurvey by Boyd W. Peterson & John A. Farmer, Cadastral Surveyors, under Group #1791, surveyed Oct. 1995/Feb. 1998. (DCSO records Vol. 52 Page(s) 19868-9)