

PRIMARY CORNER DESCRIPTION East 1/4 Cor. Sec. 5 only

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1672)

Set sandstone 12 x 10 x 8 ins., 9" in the ground on steep hillside sloping S. for ¼ sec. corner, marked ¼ on the W. side, from which,
A Fir 10" dia., bears N.82°E., 21 lks. dist. mkd. ¼ S BT.
A Fir 24" dia., bears S.47°W., 101 lks. dist. mkd. ¼ S BT

V.T. Hosford - For: Evans Products Co. - Aug. 1954 - C.S. File 41/292 and M 10-80

I find the East 1/4 S 5.
I found the original stone corner and two original BTs living.

BLM resurvey by Joel E. Robb, Cadastral Surveyor, under Group #1281, surveyed Aug/Oct. 1985 - (DCSO records Vol. 48 Page(s) 18193)

Point for the ¼ sec. cor. of sec. 5 only, determined by the method of irregular boundaries, based on the 1954 record by Hosford, when this corner was still in existence; there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:
T 22 S R 9 W
¼ S 5
1985

from which
A Fir 19" dia., bears S.59°W., 51 lks. dist. mkd. ¼ S5 BT.
A Fir 44" dia., bears N.14°W., 33 lks. dist. mkd. ¼ S5 BT.