

PRIMARY CORNER DESCRIPTION NE Cor. Sec. 33 (NW cor. Sec. 34)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #279, dated March 5, 1878, - (DCSO records Vol. 4 Page(s) 1654)

-----  
Set a Maple post 4 ft. long, 4" dia., 18" in ground, for corner to secs. 27, 28, 33 and 34, from which,  
A Fir 40" dia., bears N.15°E., 158 lks. dist.  
A Fir 24" dia., bears S.28°E., 73 lks. dist.  
A Fir 36" dia., bears S.55°W., 98 lks. dist.  
A Maple 10" dia., bears N.80°W., 77 lks. dist.

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1692)

-----  
The corner to secs. 33 and 34, which I reestablished, as follows:  
Set Maple post 4½ ft. long, 4" sq., 24" in the ground, on steep hillside sloping E., marked T22S S34 on the SE.; R9W S33 on the SW. faces with 1 notch on the S. and 3 notches on the E. edges, from which,  
A Fir 40" dia., bears N.15°E., 141 lks. dist. mkd. T22S R9W S27 BT.  
A Fir 24" dia., bears S.15°E., 95 lks. dist. mkd. T22S R9W S34 BT.  
A Fir 36" dia., bears S.40°W., 115 lks. dist. mkd. T22S R9W S33 BT.  
A Maple 10" dia., bears N.80°W., 77 lks. dist. mkd. T22S R9W S28 BT.  
Only one bearing tree agrees with notes furnished me by the U.S. Survey General. I destroyed the BT on N.

BLM resurvey by Harvey Wofford; Wayne Rogers and Owen Chatters II, Cadastral Surveyors under Group #'s 811 and 1000 - surveyed Aug. 1973/Oct. 1979 - (DCSO records Vol. 40 Page(s) 16044)

-----  
The cor. of secs. 33 and 34 only, determined at record bearing and distance from the remains of the original bearing trees:  
A sawed Fir stump 50" dia., bears S.15°E., 95 lks. dist., with scribe marks BT visible on open blaze.  
A sawed Fir stump 50" dia., bears S.40°W., 115 lks. dist., with scribe marks R9W BT visible on bark blaze.  
At the corner point  
Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd: (Cont. Next Page)

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION NE cor. Sec. 33 (NW cor. Sec. 34)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>T 22 S R 9 W <u>S 28</u> S 33 S 34 1974</p> <p>No suitable trees available within limits.</p>
<p>Cor. Fd. and used in BLM resurvey by Malloy and Farnsworth, under Group #'s 1125 and 1226, surveyed Nov/Dec. 1982 - (DCSO records Vol. 47 Page 17915)</p>
<p>2</p>