

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 28

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1692)

-----  
Set sandstone 12 x 10 x 6 ins., 9" in the ground on steep hillside sloping North for 1/4 sec. corner, marked 1/4 on the W. side, from which,  
A Fir 36" dia., bears N.17°E., 20 lks. dist. mkd. 1/4 S BT  
A Fir 6" dia., bears N.45°W., 52 lks. dist. mkd. 1/4 S BT.

Douglas County Surveyors Office - James W. Byron, Surveyor - C.S. File 54/60-38 - Feb. 1968

-----  
Corner searched for, not found. This cor. would fall in an area of numerous slides and old burn on very steep N. slope. No trace.

BLM resurvey by Harvey Wofford; Wayne Rogers and Owen Chatters II, Cadastral Surveyors under Group #'s 811 and 1000 - surveyed Aug. 1973/Oct. 1979 - (DCSO records Vol. 40 Page(s) 16046)

-----  
The 1/4 sec. cor. of secs. 27 and 28, monumented with the original sandstone, 12 x 10 x 6 ins., loosely set on top of ground, mkd. 1/4 on top, from which the remains of the original bearing trees:

- A Fir snag 36" dia., bears N.17°E., 20 lks. dist., no marks visible.
- A Fir 32" dia., bears N.45°W., 49 lks. dist., with healed blaze. (Rec. 52 lks.)

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 22 S R 9 W  
                  1/4  
                  S 28 | S 27  
                  1975

from which new bearing trees:

- A Fir 32" dia., bears S.30°E., 15 lks. dist. mkd. 1/4 S27 BT
- A Fir 26" dia., bears West, 106 lks. dist. mkd. 1/4 S28 BT.

Deposit corner stone alongside iron post.

Cor. Fd. and used in BLM resurvey by Malloy and Farnsworth, under Group #'s 1125 and 1226, surveyed Nov/Dec. 1982 - (DCSO records, Vol. 47 Page 17917)