

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 440100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 34; & 3, T23-9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 279 survey dated March 5, 1878 (DCSO records Vol. 4 Pg 1650)

Marked a Fir tree, 48" dia., for the 1/4 sec. corner.

Douglas County Surveyors Office - James Byron, Surveyor - C.S. File 54/60-15

Corner searched for, not found. Fd. square post mkd. 2640.0 temp 1/4 cor. approx. 2 years old.

Survey by Richard J. Hintz PLS #497 - For: International Paper Co. - June 1984 - M 97-6

Set 1 1/4" x 36" Iron pipe with stamped brass cap (PLS 497 1984). Pipe set in 24" x 16" sandstone 6" above ground.
BTs - 20" Fir bears S.76°00'W., 26.9 ft. scribed.
10" Hemlock bears N.11°30'W., 6.8 ft.

BLM resurvey by Joseph M Mannix & Edith M Forkner, Cadastral Surveyors Under group No. 2727 surveyed Oct. 2013/April 2014 - (DCSO records Vol. 58 Page(s) 23213)

The 1/4 sec. cor. of secs. 3 & 34, reestablished by proportionate measurement by Hintz, in 1984. There is no remaining evidence of the original corner and this point is accepted as a careful and faithful reestablishment of the cor.; monumented with a brass tablet set flush with the top of a sandstone, 24"x16"x6", mkd.

PLS 497
T 22 S R 9 W
1/4 S 34
S 3
T 23 S
1984

from which the bearing trees mkd. by Hintz

A fir, 27" dia., bears S.76 1/4°W., 26.9 ft., with a healed blaze.

A hemlock, 19" dia., bears N.10 3/4°W., 6.7 ft., with a healed blaze.

Alongside the cor. is an orange carsonite post. Each new bearing tree has a 2 1/2"x1/4" magnetic nail (Mag Nail) driven at the base on right side center, unless otherwise noted in the corner description.

Each new corner established or remonumented has a magnet deposited in a white plastic case at the base of the stainless steel post, unless otherwise noted in the corner description.