

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. Sec. 34 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #279, dated March 5, 1878, - (DCSO records Vol. 4 Page(s) 1654)

-----  
Set Fir post, 4" dia., 4 ft. long, 20" in ground, for ¼ sec. corner, from which,  
A Fir 8" dia., bears N.50°E., 51 lks. dist.  
A Fir 60" dia., bears S.20°E., 60 lks. dist.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - Feb. 1968 - C.S. File 54/60-37

-----  
Found - 1½" I.P. with brazed cap, unrecorded.  
Orig. 8" now 36" Fir N.50°E., 33.7 ft. (face). Ring count reveals tree about 28" when scribed, find "¼ u R1" bark scribe in poor condition. Tree alive.  
Orig. 60" Fir now 60" Fir snag, S.20°E., 39.6 ft.(face). Old axe mark on bark, no scribing found.

Set Brass cap in place of I.P. mkd: County Surveyors Office  
T 22 S R 9 W  
¼ S 34  
1968

Deposit old pipe alongside.  
New BTs -13" Hemlock S.9°E., 15.2 ft. mkd. ¼ S34 CS BT.  
9" D.Fir S.81°W., 15.3 ft. mkd. ¼ S34 CS BT.  
This corner lies on moderate West slope changing to NW. slope.

Cor. Fd. and used in BLM resurvey by Wofford, Rogers and Chatters, under Group #'s 811 and 1000, surveyed Aug. 1973/Oct. 1979 - (DCSO records, Vol. 40 Pages 16043-44)

Cor. Fd. and used in BLM resurvey by Malloy and Farnsworth, under Group #'s 1125 and 1226, surveyed Nov/Dec. 1982 - (DCSO records, Vol. 47 Page 17914)

Fd. OK, June 1984 by R. Hintz, M 97-6