

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 22 and 27

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 4 Page(s) 1637)

-----  
Set Fir post 3 ft. long, 4" dia., for 1/4 sec. corner, 15" in ground, from which  
A dead Fir 60" dia., bears N.20°E., 17 lks. dist.  
A dead Fir 36" dia., bears South, 6 lks. dist.

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1711)

-----  
No evidence of 1/4 sec. cor.  
Set Alder post 4 1/2 ft. long, 4" sq., 24" in the ground in a land slide for 1/4 sec. corner, marked 1/4 S on the N. face, from which  
An Alder 10" dia., bears N.58°W., 85 lks. dist. mkd. 1/4 S BT.  
A dead Fir 48" dia., bears S.70°E., 50 lks. dist. mkd. 1/4 S BT.

BLM resurvey by Harvey Wofford; Wayne Rogers and Owen Chatters II, Cadastral Surveyors under Group #'s 811 and 1000 - surveyed Aug. 1973/Oct. 1979 - (DCSO records Vol. 40 Page(s) 16045)

-----  
Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.  
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:  
T 22 S R 9 W  
1/4  $\frac{S 22}{S 27}$   
1975

from which  
A Fir 34" dia., bears N.37 1/2°W., 15 lks. dist. mkd. 1/4 S22 BT.  
A Fir 21" dia., bears S.5 1/2°W., 73 lks. dist. mkd. 1/4 S27 BT.

BLM Corrective Dependent resurvey by Stephen J. Malloy and John P. Farnsworth, Cadastral Surveyors, under Group #'s 1125 and 1226, surveyed Nov./Dec. 1982 - (DCSO records Vol. 47 Page(s) 17916)

-----  
Point for the 1/4 sec. cor. of secs. 22 and 27, at proportionate distance; there is no remaining evidence of the original corner. (Cont. Next Page)

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 440300

PRIMARY CORNER DESCRIPTION 1/4 cor. for secs. 22 and 17

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

From this point the  $\frac{1}{4}$  sec. cor. of secs. 22 and 27, erroneously established by Wofford, etal, 1973-79, bears N.12°41'E., 0.519 chs. dist., monumented with an iron post, 2½" dia., firmly set, projecting 4" above ground, with brass cap mkd. and witnessed as described in the official record.

Remove the iron post, and at the true corner point  
Reset the iron post, 28" long, 2½" dia., 24" in the ground,  
with brass cap mkd:

T 22 S R 9 W  
                  S 22  
 $\frac{1}{4}$  —————  
                  S 27  
                  1983

from which bearing trees mkd. by Wofford, etal:

A Fir 35" dia., bears N.17°E., 66½ lks. dist. mkd.  $\frac{1}{4}$  S22  
BT.

A Fir 21" dia., bears S.9°E., 21 lks. dist. mkd.  $\frac{1}{4}$  S27 BT.

Survey by Les Roberts - For: International Paper Co. - Sept.  
1983 - M 90-52 and C.S. File 58/280(n)

-----  
Condition Report - (This report was filed previously to the  
above BLM information)

Found - 1983 BLM brass cap.

20" Fir bears S.08°E., 13.7 ft., scar visible.

34" Fir bears N.18°E., 43.0 ft., scar visible.