

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION E. 1/4 Corner for Sec. 34 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #279, dated March 5, 1878, - (DCSO records Vol. 4 Page(s) 1653)

Set Fir post, 40" long, 4" dia., 18" in ground, for ¼ sec. corner, from which,
A Fir 36" dia., bears N.45°E., 45 lks. dist.
A Fir 40" dia., bears S.20°W., 25 lks. dist.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - Feb. 6, 1968 - C.S. File 54/60-30

Found - Unrecorded 1½" I.Pipe and brazed cap mkd: "¼S34"
Orig. 40" now 52" Fir, alive, S.20°W., 16.5 ft., bark scribe in poor condition.
No trace other original BT.
40" Fir snag bears N.57°E., 34.0 ft., could not make this snag fit for other BT.

Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 9 W
¼ S 34 |
1968

Deposit old pipe alongside brass cap.
New BTs -13" D.Fir S.16°E., 30.2 ft. mkd. ¼ S CS BT.
14" D.Fir N.19°W., 47.9 ft. mkd. ¼ S34 CS BT.
Rescribe orig. BT, S.20°W., 16.5 ft. "¼ S34 CS BT" in bark alongside scribe.

This corner lies on change from moderate to steep easterly slope.

Fd. B.C., June 1984, R. Hintz, M 97-6