

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION Sec. cor. for 22, 23, 26 and 27

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 4 Page(s) 1635)

-----  
Set a granite stone 16 x 12 x 6 ins., 10" in ground for the corner to secs. 22, 23, 26 and 27.  
No live timber near. No witness trees.

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1687-88) (and duplicated on Page 1706)

-----  
The Sec. cor., which is a granite stone, 10 x 8 x 4 ins. above ground, mkd. with 2 notches on the S. and E. sides, I marked:

- A dead Fir 50" dia., bears N.42°E., 29 lks. dist. mkd. T22S R9W S23 BT.
- A dead Fir 48" dia., bears S.55°E., 52 lks. dist. mkd. T22S R9W S26 BT.
- A dead Fir 24" dia., bears S.51°W., 118 lks. dist. mkd. T22S R9W S27 BT.
- A dead Fir 36" dia., bears N.41°W., 88 lks. dist. mkd. T22S R9W S22 BT.

BLM resurvey by Harvey Wofford; Wayne Rogers and Owen Chatters II, Cadastral Surveyors under Group #'s 811 and 1000 - surveyed Aug. 1973/Oct. 1979 - (DCSO records Vol. 40 Page(s) 16036)

-----  
Point for the cor. of secs. 22, 23, 26 and 27, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28" long, 2½" dia., 22" in the ground, with brass cap mkd:

T 22 S R 9 W  
S 22 | S 23  
S 27 | S 26  
1974

from which

- A Fir 8" dia., bears N.63°E., 22 lks. dist. mkd. T22S R9W S23 BT.
- A Fir 20" dia., bears S.75°E., 22 lks. dist. mkd. T22S R9W S26 BT.
- A Fir 22" dia., bears S.54°W., 11 lks. dist. mkd. T22S R9W S27 BT.
- A Fir 12" dia., bears N.49°W., 14 lks. dist. mkd. T22S R9W S22 BT.

(Cont. Next Page)

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION Sec. cor. for 22, 23, 26 and 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Survey by Les Roberts, PLS #1039 - For: International Paper Co. - Sept. 1983 - C.S. File 58/280 and M 90-52

-----  
Condition Report Only - (Note: this report on cor. filed previous to the approval of BLM resurvey as described below)

Found - 1983 BLM brass cap.  
6" x 8" x 10" stone with 2 notches on S. & E. edges.  
30" Fir stump bears N.41°W., 35.0 ft., no marks,  
(Rec. N.41°W., 58.1 ft.)  
46" Fir snag bears N.41°E., 18.8 ft., no marks.  
48" Fir snag bears S.65°E., 65.0 ft., no marks.  
(Rec. S.55°E., 34.3 ft.)  
11" Fir bears N.55°E., 33.6 ft., scribe visible,  
(Rec. N.59°E., 33.7 ft.)  
12" Fir bears S.87°E., 33.3 ft., scribe visible.  
17" Fir bears S.76°W., 55.9 ft., scribe visible.  
18" Fir bears N.88°W., 73.2 ft., scribe visible.

BLM Corrective Dependent resurvey by Stephen J. Malloy and John P. Farnsworth, Cadastral Surveyors, under Group #'s 1125 and 1226, surveyed Nov./Dec. 1982 - (DCSO records Vol. 47 Page(s) 17908-09)

-----  
The sec. cor., monumented with the original sandstone 10 x 8 x 4 ins., loosely set, projecting 3" above ground, mkd. with 2 notches on S. and E. edges, from which the remains of the original bearing trees:

- A Fir snag 45" dia., bears N.37°E., 29 lks. dist., no marks visible on decayed remains. (Rec. N.42°E.)
- A root hole bears S.55°E., 52 lks. dist. with a downed, decayed Fir, size indeterminate, alongside, no marks visible.
- A Fir stump 35" dia., bears N.41°W., 52 lks. dist., no marks visible on decayed remains. (Rec. 88 lks.)

From this point, the sec. cor. erroneously reestablished by Wofford, etal, 1973-79, bears N.2°33'W., 1.034 chs. dist. monumented with an iron post, 2½" dia., firmly set, projecting 6" above ground, with brass cap mkd. and witnessed as described in the official records.

Remove the iron post, destroy the marks on the bearing trees, and at the true corner point:  
Reset the iron post 28" long, 2½" dia., 25" in the ground, with brass cap mkd:

(Cont. Next Page)

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION Sec. cor. for 22, 23, 26 and 27

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

<p>T 22 S R 9 W S 22   S 23 S 27   S 26 1983</p>
<p>from which new bearing trees: A Fir 10" dia., bears N.59°E., 51 lks. dist. mkd. T22S R9W S23 BT. A Fir 13" dia., bears S.87°E., 50 lks. dist. mkd. T22S R9W S26 BT. A Fir 18" dia., bears S.76½°W., 86 lks. dist. mkd. T22S R9W S27 BT. A Fir 20" dia., bears N.87°W., 113 lks. dist. mkd. T22S R9W S22 BT. Deposit the original stone alongside the iron post. Corner is located in a ravine, drains W.</p>
<p>Brent Knapp - For: Roseburg Resources - 2/24/2025 - M184-62 ----- Found - Brass cap marked "t22S R9W ¼ S23/S26 1974" Stump remnant N.18°W 20.8'. "X" in 4'x5'x4' boulder S.29°E. 4.2'. Root hole S.82°E. 23.1'. 36" Maple S.06°E. 16.5' no marks. New - 9" D. Fir N.25°E. 15.6' scribed "¼ S23 BT" 10" D. Fir N.55°E. 20.6' scribed "¼ S23 BT" "X" in 4'x5'x4' boulder S.29°E. 4.2'. O CRS COORDINATE SYSTEM COTTAGE GROVE-CANYONVILLE ZONE</p>
<p>3</p>