

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3, 10, & 11

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original GLO Survey by W.H. Byars, Deputy Surveyor, under contract # 202, dated March 11, 1875 (DCSO records Vol. 4 Page(s) 1626)

-----  
Set - Fir post, 3' long 18" in ground, 5" dia.  
BT's- 50" dia., Fir, bears S.68°E., 22 lks.  
16" dia., Fir, bears N.80°W., 79 lks.

GLO Resurvey by Elmer O. Worrick, Deputy Surveyor, under contract #632, dated April 28, 1894 (DCSO records Vol. 4 Page(s) 1704)

-----  
After diligent search, unable to find any trace of the corner  
Set- Hemlock post 4½' long, 5" square, 24" in the ground on  
a steep hillside sloping NE.

New Bt's -  
20" dia. Alder, bears N.9°E., 62 lks., mkd. T22S R9W,  
S2 B.T.  
14" dia. Maple, bears S.11°30'E., 49 lks., mkd. T22S  
R9W, S11 B.T.  
30" dia. Fir, bears S.38°W., 34 lks., mkd. T22S R9W,  
S10 B.T.  
16" dia. Maple, bears N.30°30'W., 27 lks., mkd. T22S  
R9W, S3 B.T.

Victor McLind - for: Menasha Corp. - Dec. 1996 - M 126-23

-----  
Mon. Fd.- 2" I.P. with 3½" BLM Brass cap, marked T22S R9W  
S3 S2 S10 S11 1995" B.T.S.

Bt's Fd.- 49" Fir stump, healed face S.38°W., 22.4'. OBT  
12" Fir, scribes visible, N.64°E., 23.4'.  
13" Fir, scribes visible, S.53°E., 19.4'.  
12" Fir, scribes visible, S.61°W., 18.7'.  
13" Fir, scribes visible, N.52°W., 19.9'.

History: Original survey by W.H. Byars in 1874. E.O.  
Worrick reestablished corner in 1894 after  
failing to find Byars' corner. BLM set corner  
in 1995 from Worrick's SW B.T. BLM survey not  
yet official.

Dependent resurvey by Boyd W. Peterson & John A. Farmer,  
Cadastral Surveyors, under Group #1791, surveyed Oct.  
1995/Feb. 1998. (DCSO records Vol. 52 Page(s) 19862-3)

-----  
The cor. of secs. 2, 3, 10 and 11, determined at record  
bearing and distance from the remains of a bearing tree mkd.  
by Worrick:

continued next page

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3, 10, & 11

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A fir stump, 40" diam., bears S.38°W., 34 lks., with scribe marks 22S visible on an opened blaze.  
At the corner point  
Set a stainless steel post, 28" long, 2½" diam., 24" in the ground, with brass cap mkd.

T 22 S R 9 W  
S 3 | S 2  
S 10 | S 11  
1995

and new bearing trees

A fir, 12" diam., bears N.68°E., 35½ lks. dist., mkd. T22S R9W S2 BT.

A fir, 13" diam., bears S.52°E., 31½ lks. dist., mkd. T22S R9W S11 BT.

A fir, 12" diam., bears S.60°W., 28 lks. dist., mkd. T22S R9W S10 BT.

A fir, 12" diam., bears N.48 3/4°W., 28 lks., mkd. T22S R9W S3 BT.

Deposit a magnet in a white plastic case at the base of the stainless steel post.

Gary Smithers - For: Roseburg Resources Co. - Oct 2005 - M148-73

-----  
Found - 1995 BLM brass cap, DCSO recs Vol 52 Pg 19862-3  
40" Fir rotting stump S.38°W., 22.4 ft. with visible scribes and tag  
12" D.Fir N.68°E., 23.4 ft. with healed face & tag  
15" D.Fir S.52°E., 20.8 ft. with healed face & tag  
14" D.Fir S.60°W., 8.5 ft. with healed face & tag  
Record 12" D.Fir N.48°W., 18.5 ft. has fallen down  
New BTs- 16" D.Fir N.34°W., 31.5 ft. scribed T22 R9 S3 BT to spike set side center with bearing tree tag