

PRIMARY CORNER DESCRIPTION SE Corner for Sec. 27

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1689)

-----

Set Dogwood post 4½ ft. long, 4" sq., 24" in the ground, for the SE. corner of sec. 27, marked T22S S35 on the SW.; R9W S27 on the NW. faces, with 1 notch on the S. and 2 notches on the E. edge, from which,

A Fir 12" dia., bears N.55°E., 74 lks. dist. mkd. T22S R9W BT.

A Fir 30" dia., bears S.62°W., 91 lks. dist. mkd. T22S R9W S35 BT.

A Fir 16" dia., bears N.66°W., 21 lks. dist. mkd. T22S R9W S27 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - Feb. 1968 - C.S. File 54/60-36

-----

Found - Orig. 12" Fir, now down and badly decayed, N.55°E., 48.8 ft. find old axe marks, no scribe.

Orig. 30" now 48" Fir, alive, S.62°W., 60.1 ft., open and find axe notch.

Orig. 16" now 40" Fir, alive, N.66°W., 13.9 ft., shows good scar, do not open.

Set Brass cap at cor. mkd: County Surveyors Office

T 22 S R 9 W

S 27 |

1968

New BTs -8" Hemlock N.52°W., 39.5 ft. mkd. T22S R9W S27 CSBT

11" Hemlock S.77°W., 80.9 ft. mkd. T22S R9W S35 CSBT

10" Hemlock N.35°E., 35.1 ft. mkd. T22S R9W CS BT.

This corner lies on S. edge of bench approx. 100 ft. N. of creek, course E.

Cor. Fd. and used in BLM resurvey by Wofford, Rogers and Chatters, under Group #'s 811 and 1000 - surveyed Aug. 1973/Oct. 1979 - (DCSO records Vol. 40 Page(s) 16035)

Fd. and used in BLM corrective dependent resurvey by Malloy and Farnsworth, under Group #'s 1125 and 1226, surveyed Nov/Dec. 1982 - (DCSO records, Vol. 47 Pages 17907)