

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 529100

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. Sec. 2 only, T23-9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 279 survey dated March 5, 1878 - (DCSO records, Vol. 4 Page 1651)

Set Fir post 6" dia., 4 ft. long, 20" in ground, from which
A Fir 16" dia., bears East, 35 lks. dist.
A Fir 8" dia., bears West, 52 lks. dist.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - Dec. 1967 - C.S. File 54/60-12

Found - 1½" Iron pipe and brazed iron cap, unrecorded.
Orig. 16" now 38" Fir, alive, East 23.1 ft. shows scar, do not open.
Orig. 8" now 30" Fir, now down, West 34.3 ft., broken off stump in place, scribed "¼".

Set Brass cap at cor. mkd: County Surveyors Office
T 22 S
T 23 S R9W ¼ _____
S 2
1967

New BTs -16" Maple S.89°W., 14.2 ft. mkd. ¼ S2 CS BT.
7" D.Fir S.31°E., 18.4 ft. mkd. ¼ S2 CS BT.

Deposit iron pipe alongside brass cap. This corner lies on moderate North slope of ridge.

Fd. and used in BLM survey by Wofford and Malloy, under Group #1074, surveyed July 1980/Nov. 1982 - (DCSO records, Vol. 43 Page 16854)