

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 23 and 26

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 4 Page(s) 1635)

Set sandstone 18 x 12 x 6 ins., 12" in ground, for the 1/4 sec. corner, from which
A Fir 16" dia., bears North, 18 lks. dist.
No other tree near South of line.

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1706)

Could not find stone.
I set sandstone 12 x 12 x 8 ins., 8" in ground on hillside sloping South, mkd. 1/4 S on North face, from which
A Fir 16" dia., bears North 18 lks. dist. mkd. 1/4 S BT. As this tree had been blown down, I marked:
A Maple 6" dia., bears S.6°E., 25 lks. dist. mkd. 1/4 sec. BT.
A Fir 24" dia., bears N.18°W., 35 lks. dist. mkd. 1/4 sec. BT.

BLM resurvey by Harvey Wofford; Wayne Rogers and Owen Chatters II, Cadastral Surveyors under Group #'s 811 and 1000 - surveyed Aug. 1973/Oct. 1979 - (DCSO records Vol. 40 Page(s) 16037)

The 1/4 sec. cor., monumented with a sandstone 12 x 12 x 8 ins., firmly set 8" in the ground, mkd. 1/4 on N. face, from which the remains of bearing trees by Worrick:
A decayed Fir stump 30" dia., bears N.18°W., 35 lks. dist., with scribe marks BT visible on opened blaze.
A Maple 30" dia., bears S.6°E., 25 lks. dist. with healed blaze.

At the corner point
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:
T 22 S R 9 W
1/4 S 23
S 26
1974

from which new bearing trees
A Fir 12" dia., bears N.49 1/2°E., 59 lks. dist. mkd. 1/4 S23 BT.
A Fir 9" dia., bears S.82°E., 35 lks. dist. mkd. 1/4 S26 BT.
Deposit corner stone alongside iron post.

(Cont. Next Page)

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 540300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 23 and 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Cor. Fd. and used in BLM resurvey by Malloy and Farnsworth, under Group #'s 1125 and 1226, surveyed Nov/Dec. 1982 - (DCSO records, Vol. 47 Pages 17909-10)

Found OK by R. Quimby, February 1997 - M 124-42

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2149, surveyed Aug. 2006/Oct. 2006 - (DCSO records Vol. 55 Page(s) 21726-27)

The ¼ sec. cor. of secs. 23 and 26, monumented with an iron post, 2½" dia., firmly set, projecting 2" above ground, with brass cap (properly) mkd. from which the remains of the bearing trees mkd. by Worrick in 1894
 A maple, 33" dia., bears S.6°E., 16.5 ft., no marks visible.
 A burned fir stump, size indeterminate, bears N.18°W., 20.8 ft., no marks visible. (Record, 23.1 ft.)
and the remains of a bearing tree mkd. by Wofford, Rogers, and Chatters in 1973-79
 A roothole bears N.49½°E., 38.9 ft., with a down fir, 16" dia., alongside, with a healed blaze.
and the remains of a bearing tree mkd. by person(s) unknown
 A burned fir stump, 9" dia., bears S.82°E., 23.1 ft., with scribe marks ¼ S26 BT visible on burned partially healed blaze.
No suitable trees to the N. available.
Corner is located nearly under down decayed fir log, 3 ft dia., in fir reproduction.

Brent Knapp - For: Roseburg Resources - 2/24/2025 - M184-62

Found - 1972 BLM Brass cap (properly mkd)
 Stump remnant N.18°W., 20.8'
 "X" in 4'x5'x4' boulder S.29°E., 4.2'
 Root hole S.82°E., 23.1'
 36" Maple S.6°E., 16.5' no marks
New - 9" D.Fir N.25°E., 15.6' scribed "¼ S23 BT"
 10" D.Fir N.55°E., 20.6' scribed "¼ S23 BT"
 "X" in 4'x5'x4' boulder S.29°E., 4.2.