

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 540500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCS0 records Vol. 4 Page(s) 1626)

Set a Fir post, 40" long, 5" dia., 20" in ground, for ¼ sec. cor. from which,
A Fir 5" dia., bears S.5°W., 58 lks. dist.
A Fir 30" dia., bears N.30°W., 114 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; A. Bilow - July 25, 1958 - C.S. File 49/103-1

Found - Orig. 30" now 42" Fir stump N.30°W., 75.2 ft. Old bark scribing "S" near top of stump.
No trace of orig. SW BT found.

Corner checks call to creek. Corner in Weatherly Creek Road. I set WITNESS CORNER 20 ft. West.

Set Brass cap at witness point mkd: County Surveyors Office
Wit. Cor. ¼ S11 T22S R9W
S14
¼ Cor. 20' East
1958

New BTs -24" R.Fir bears N.6½°E., 40.5 ft. scribed WC ¼ S11
CS BT.

30" R.Fir bears N.55°E., 159.5 ft. scribed WC ¼ S11
CS BT.

No suitable trees near to South.

Fd. OK, DCS0, V.R.T., Dec. 27, 1967 - C.S. File 54/60-18

Mark Smalley, for Scott Timber Co. - May 1997 - M 127-9

Found - 1958 County BCIP set by Byron for Witness Corner (¼ corner 20 ft. east in road)
1/4 OBT - 30" Fir, N.30°W., 114 lks., rotted stump, Byars BT for ¼ corner.

Found W.C. BTs -

30" Fir, N.6½°E., 40.5 ft. - healed

38" Fir, N.55°E., 159.5 ft. - healed

New BTs- 7" Oak, S.82°W., 19.0 ft. scribed "¼ WC BT"

9" Alder, N.30°E., 79.5 ft. scribed "¼ WC BT"

Fd. Ok by Gary Smithers - Oct 2005 - M148-73