

PRIMARY CORNER DESCRIPTION C C for Secs. 35 and 36 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1687)

Set Hemlock post 4½ ft. long, 4" sq., 24" in the ground at point of intersection for closing corner to secs. 35 and 36, mkd. C. C. on the N.; T22S S36 on the E.; and R9W S35 on the W. sides, with 1 groove on the E. and 5 grooves on the W. sides, from which

 A Fir 24" dia., bears N.44°E., 58 lks. dist. mkd. T22S R9W S36 BT.

 A Fir 36" dia., bears S.37°E., 27 lks. dist. mkd. C.C. T22S R9W S35-36 BT.

 A Fir 36" dia., bears N.58°W., 45 lks. dist. mkd. T22S R9W S35 BT.

Douglas County Surveyors Office - James W. Byron, Surveyor - C.S. File 54/60-13 - Dec. 13, 1967

Corner searched for, not found.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - Feb. 1968 - C.S. File 54/60-31

Found - Unrecorded 1½" I.P. at corner, nearly flush with ground.

 Orig. 24" Fir now 36" stump, N.44°E., 38.3 ft., shows scar. Do not open.

 Orig. 36" Fir, now 42" stump, S.33°E., 17.8 ft., burned. Open and find "2S" scribe and reverse.

 Orig. 36" Fir now 44" stump, N.58°W., 29.7ft., open and find scribed "S".

Set Brass cap at cor. mkd: County Surveyors Office

T 22 S	R9W	<u>S 35</u>	<u>S 36</u>	CC
T 23 S		1968		

Deposit I.P. alongside.

New BTs -9" D.Fir N.43½°E., 27.1 ft. mkd. T22S R9W S36 CC CS BT.

 9" D.Fir N.50°W., 74.9 ft. mkd. T22S R9W S35 CC CS BT.

This corner lies on steep, south slope in old logged area.

Fd. OK, Jan. 13, 1983 by R. Luckman - M 93-41

(Cont. next page)

1

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 600100

PRIMARY CORNER DESCRIPTION CC Secs. 35 & 36 only.

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Mark Smalley - For: Roseburg Forest Products - Bill Olson -
Ralph McManis - Nov 1998 - C.S. File 65/23-3

Found - 1968 DCSO BC IP
36" Fir stump N.58°W., rotted - open - visible
scribe.
17" Fir, N.43½°E., 27.1 ft., good - healed face.
48" Fir stump S.30°E., 16.5 ft., rotted - open -
visible scribe.
New BTs- 15" Fir, East 6.0 ft., scribed "S36 BT"
18" Fir, N.32°E., 9.3 ft., scribed "S36 BT"
17" Fir, N.78°W., 34.7 ft., scribed "S35 BT"