

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1683)

Set a Fir post 4½ ft. long, 4" sq., 24" in the ground on level bench for ¼ sec. corner, mkd. ¼ S on the West face, from which,
A Fir 30" dia., bears N.88°E., 26 lks. dist. mkd. ¼ S BT.
A Fir 12" dia., bears West, 68 lks. dist. mkd. ¼ S BT.
(A Fir 24" dia., a line tree marked with 2 notches on the N. and S. sides, bears N.0°01'W., 0.75 chs.)

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - Jan. 1968 - C.S. File 54/60-27

Found - Unrecorded 1½" I.P. and brazed cap mkd. ¼ S25|S26.
Orig. 30" now 36" Fr, N.88°E., 17.2 ft., now down, laying face down.
Orig. 12" now 30" Fir, West 44.9 ft., now badly decayed stump.

Set Brass cap at exact point mkd: County Surveyors Office
T 22 S R 9 W
¼ S26|S25
1968

Deposit Iron pipe alongside.
New BTs -8" D.Fir S.51°E., 49.2 ft. mkd. ¼ S25 CS BT.
9" D.Fir S.11°W., 64.4 ft. mkd. ¼ S26 CS BT.
This corner lies on flat bench on ridge top, course N. & S.

Fd. OK, Jan. 1983 by R. Luckman, M 93-41

Mark Smalley - For: Roseburg Forest Products - Bill Olson - Ralph McManis - Nov 1998 - C.S. File 65/23-2

Found - 1968 DCSO BC
19" Fir, S.51°E., 49.2 ft., Good condition - healed face.
25" Fir, S.11°W., 64.4 ft., Good condition - healed face.
New BTs- 21" Fir, N.76°W., 23 ft., scribed "¼ S BT"
17" Fir, N.4°E., 64.4 ft., scribed "¼ S BT"

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2149, surveyed Aug. 2006/Oct. 2006 - (DCSO records Vol. 55 Page(s) 21735-36)

The ¼ sec. cor. of secs. 25 & 26, remonumented by the Douglas County Surveyors Office, in 1968; monumented with cont.

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

an iron post, 1" dia., firmly set, projecting 14 ins. above ground, with brass cap (properly) mkd.
from which the remains of the original bearing trees
A roothole bears N.88°E., 17.2 ft., with a down shattered fir, size indeterminate, alongside, no marks visible.
A decayed fir stump, size indeterminate, bears West, 44.9 ft., with illegible scribe marks visible on open blaze.
and the BTs mkd. by the Douglas County Surveyor in 1968
A fir, 21" dia., bears S.51°E., 49.2 ft., with a healed blaze.
A fir, 29" dia., bears S.11°W., 64.4 ft., with a healed blaze. Tree is behind a fir, 24" dia., 10 ft. from the cor., with axe marks X at breast height.
and bearing trees mkd. by Smalley, in 1998
A fir, 19" dia., bears N.2½°E., 34.7 ft., with a healed blaze.
A fir, 24" dia., bears N.76½°W., 23.2 ft., with a healed blaze.