

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 700200

PRIMARY CORNER DESCRIPTION C C for secs. 25 & 36 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1685)

Set Hemlock post, 4½ ft. long, 4" sq. 24" in the ground at the point of intersection for the closing cor. to secs. 25 and 36, marked C. C. on the W., T22S S25 on the N.; and R9W S36 on the S. faces, with 1 groove on the S., and 5 grooves on the N. sides, from which
A Fir 30" dia., bears S.86°E., 68 lks. dist. mkd. C C T22S R9W S25-36 BT.
A Fir 8" dia., bears S.25°W., 62 lks. dist. mkd. T22S R9W S36 BT.
A Fir 24" dia., bears N.67°W., 66 lks. dist. mkd. T22S R9W S25 BT.
(Corner is North, 420 lks. of cor. to Secs. 30 and 31 only, T22-8)

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone & Vernon Tracy, crew - Jan. 18, 1963 - C.S. File 49/103-9

Found - 52" Fir S.68°E., 44.9 ft. chopped open and found good reverse scribing.
28" Fir S.25°W., 40.9 ft. shows good axe scar.
Rescribe "T22S R9W S36 CS BT"
48" Fir N.67°W., 43.6 ft. shows good axe scar, injury on NW face shows tree rotting in center.
(All distances on old BTs are slope dist. from center of trunk)

Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 9 W
CC $\frac{S25}{S36}$ | R8W
1963
New BTs -11" D.Fir N.66°E., 22.3 ft. mkd. CC S25 S36 CS BT.
8" D.Fir N.38°W., 16.7 ft. mkd. T22S R9W S25 CS BT.
Corner lies nearly at foot of steep South slope, in upper edge of cut bank on old logging road.

Fd. and used in BLM resurvey by Brooks and Peterson, under Contract #'s 595 and 657 - surveyed Aug. 1965/Dec. 1967 - (DCSO records, Vol. 34 Page 14106)

Fd. OK, Jan. 13, 1983, by R. Luckman, M 93-41

continued next page

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 700200

PRIMARY CORNER DESCRIPTION CC for secs. 25 & 36 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2149, surveyed Aug. 2006/Oct. 2006 - (DCSO records Vol. 55 Page(s) 21727-28)

The closing cor. of secs. 25 and 36, remonumented by the Douglas County Surveyors Office in 1963, and accepted by Brooks and Peterson in 1965-67; monumented with an iron post, 1 in. diam., firmly set, projecting 10" above ground, with brass cap (properly) mkd.

from which the remains of the original bearing trees
A fir stump, 60" dia., bears S.88°E., 44.9 ft., no marks visible.

A fir stump, 30" dia., bears S.25°W., 38.8 ft., no marks visible. (Record, 40.9 ft.)

A decayed fir stump, size indeterminate, bears N.61¼°W., 40.3 ft., with illegible scribe marks visible on opened healed blaze. (Record, N.67°W., 42.2 ft.)

and the BTs mkd. by the Douglas County Surveyors Office, in 1963, and reported by Brooks and Peterson in 1965-67

A fir, 21" dia., bears N.66°E., 21.8 ft., with a healed blaze.

A fir, 18" dia., bears N.39°W., 15.8 ft., with a healed blaze. (Record, 16.5 ft.)

and a new bearing tree

A hemlock, 6" dia., bears S.19°W., 15.2 ft., mkd. T22S R9W S36 CC BT.

Corner is located on the SE. cor. of timber, edge bears N. and W., with older fir reproduction to the S. and E.