

TOWNSHIP 22 RANGE 10 POINT IDENTIFIER # 271700

PRIMARY CORNER DESCRIPTION So. Sec. cor. for 32 & 33 only, T21-10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1046)

Set an Iron post, 3 ft. long, 2" dia., 24" in the ground, for cor. of secs. 32 and 33, with brass cap mkd:
$$\begin{array}{r} \text{T21S R10W} \\ \text{S32|S33} \\ \hline 1919 \end{array}$$

from which

A Willow 12" dia., bears N.60°E., 46 lks. dist. mkd. T21S R10W S33 BT.

A Fir 16" dia., bears N.65°W., 57 lks. dist. mkd. T21S R10W S32 BT.

Douglas Co. Surveyors Office - Bruce Rogers, Deputy and crew - April 1965 - C.S. File 54/1-25

Found - GLO brass cap at corner, mkd. 1919.
16" Fir now 30" snag, N.65°W., 37.6 ft., chopped out, found good scribing "R"
No trace of NE BT.

Set Brass cap 34 ft. S. of cor. mkd: County Surveyors Office
$$\begin{array}{r} \text{T21S} \\ \text{T22S} \end{array} \begin{array}{r} \text{R10W} \\ \text{R10W} \end{array} \begin{array}{r} \text{S 32|S 33} \\ \text{35' N.to cor} \\ \hline 1965 \end{array}$$

New BTs -26" Fir N.17°E., 6.8 ft. mkd. W.C. T22S R10W S5 CS BT.
24" Fir S.75°E., 15.4 ft. mkd. W.C. T22S R10W S5 CS BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - May 15, 1968 - C.S. File 54/1-2

Found - 1965 C.S. Brass cap and stumps of BTs.
26" Fir stump N.17°E., 6.8 ft., scribe visible on pitched blaze.
24" Fir stump S.75°E., 15.4 ft. scribe visible on pitched blaze.

Set 6 ft. steel fence post alongside brass cap.
No trees available for new BTs.
Corner lies 35 ft. South of U.S.F.S. Rd. #2173 on top of cut bank in logged off area.

(Cont. Next Page)

TOWNSHIP 22 RANGE 10 POINT IDENTIFIER # 271700

PRIMARY CORNER DESCRIPTION S. Sec. cor. for 32 & 33 only, T21-10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - May 24, 1968 - C.S. File 54/1-3

Found - 1965 C.S. brass cap and sawed stumps of BTs as follows:

26" Fir stump N.17°E., 6.8 ft., scribe visible. Set 5/8" x 30" Iron rod on bearing at 5.4 ft. from Wit. Cor. at base of BT.

24" Fir stump S.75°E., 16.9 ft. (not 15.4 ft.) scribe visible. Set 5/8" x 30" Iron rod 15.6 ft. from Wit. Cor. at base of BT.

Set 6 ft. steel fence post alongside brass cap.

No trees available for new BTs.

Wit. Cor. lies on top of cut bank 35 ft. South of U.S.F.S. Rd. #2138.

At true corner point, SET 5/8" Iron rod x 15". Sandstone in roadway flush with surface 3.0 ft. W. of ditch line. Wit. Cor. bears South 34 ft.

The 5/8" x 30" I.Rods set at base of Wit. Cor. BTs. as follows, from 5/8" x 15" Iron rod set at true corner point on edge of roadway:

5/8" x 30" I.R. bears S.19°E., 58.3 ft. This rod is 6" above ground at base of Wit. Cor. BT. to SE.

5/8" x 30" I.R. bears S.3°E., 28.0 ft. This rod is 6" above ground at base of Wit. Cor. BT to NE.