

PRIMARY CORNER DESCRIPTION West 1/4 Cor. for Sec. 9 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Aurelius Todd, Deputy Surveyor, under Contract #629, dated April 24, 1894 - (DCSO records Vol. 5 Page(s) 1819)

Set a sandstone 12x8x6 ins., 9" in the ground for ¼ sec.cor. mkd. ¼ S. on W. face, from which
A Fir 36" dia., bears N.20°E., 27 lks. dist. mkd. ¼ S BT.
A Fir 4" dia., bears S.82°W., 30 lks. dist. mkd. ¼ S BT.

Douglas County Surveyors Office - Fritz Ingram, Surveyor - crew L.E. Monrean; P.Earle; V. Cangie - Aug. 12, 1976 - C.S. File 59/18-17

Corner searched for, not found. Report of what found:
A Stone 15x9x7 ins. setting on surface. (Rec. 12x8x6, 9" in the ground) "¼S" mkd. on West face, the vertical measurement being 7" indicates that the stone has been broken.
A Fir 42" dia., bears S.77°E., 16.0 ft. Tagged by Haines as ¼ S9 only. Forest Service tag indicates a distance of 15 ft. to S9 only. Tree tagged by Forest Service, Feb. 28, 1968 by D.H.D. & W.H.
Approx. 15" dia. Fir bears N.68°E., 8.0 ft. Tagged by same as above tree. Tag indicates 7 ft. distance to corner.
A Fir approx. 12" dia. is about 150 ft. North of ¼ S9. Tree is tagged ¼ S8. Tree tagged by Forest Service Feb. 28, 1976 by D.H.D. & W.H.
A Fir approx. 12" dia. is tagged by Forest Service ¼ S8, East 16 ft. Tagged by D.H.D. & W.H.

Survey by Ronald Stuntzner - For: U.S. Forest Service, Siuslaw National Forest - Sept. 1989 - M 108-75

Found - Original corner stone with ¼ S chiseled on West face.
4" D.Fir now 43", S.77°W., 15.3 ft. faintly visible face on NW quad. (1894 BT)
36" D.Fir now rotted remains, N.18°E., 21.3 ft. (1894 BT)
Set 2" x 30" alum. pipe with 3" alum. cap mkd. "T22S R10W 1/4|S9 1989 LS 1342". Placed stone face down on East side of cap.
New BTs -17" D.Fir N.65°E., 8.0 ft. scribed ¼ S9 BT.
13" D.Fir N.19°E., 24.0 ft. scribed ¼ S9 BT.