

TOWNSHIP 22 RANGE 10 POINT IDENTIFIER # 533700

PRIMARY CORNER DESCRIPTION South 1/4 Cor. for Sec. 35 only, T21-10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1040-41)

Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for
¼ sec. cor. of sec. 35 only, with brass cap mkd: ¼ S35
1919

from which

A Fir 6" dia., bears N.21°E., 16 lks. dist. mkd. ¼ S35 BT.
A Fir 16" dia., bears N.79°W., 6 lks. dist. mkd. ¼ S35 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - May 1968 - C.S. File 54/1-32

Found - 1919 brass cap, broken off, concrete filled I.P. in place.

6" now 7" Fir, decayed stub, N.21°E., 10.6 ft., shows fragmentary scribe.

16" now 22" Fir N.79°W., 4.0 ft., alive, shows good scar. We do not open.

Set Brass cap at cor. mkd: County Surveyors Office
T21S R10W ¼ S 35
T22S 1968

Deposit old corner materials alongside.

New BTs -10" D.Fir N.76°E., 13.7 ft. mkd. "¼ S35 CS BT"

22" D.Fir N.79°W., 4.0 ft. rescribed "¼ S35 CS BT"

This cor. lies on steep SW. slope approx. 85 ft. W. of top of spur, ridge sloping South.