

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25, 26, 35 and 36

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W.H. Byars, Deputy Surveyor under contract # 274 survey dated Sept. 10, 1877 (DCSO records Vol. 4 Pg 1737)

Marked a Fir, 5" dia., for the cor. to secs. 25, 26, 35 and 36, from which

- An Alder 20" dia., bears N.65°E., 67 lks.
- A Maple 5" dia., bears S.40°E., 63 lks.
- A Fir 5" dia., bears S.42°W., 64 lks.
- A Maple 24" dia., bears N.30°W., 121 lks.

GLO survey by Aurelius Todd, Deputy Surveyor, under Contract #629, dated April 24, 1894 - (DCSO records Vol. 4 Page(s) 1768-69)

This cor. being in bad condition, I remark the trees and establish the cor. as follows:

A Fir 16" dia., for cor., marked T22S S25 on NE.; R10W S36 on SE.; S35 on SW.; S25 on NW. faces, with 1 notch on S. and E. edges, from which

- An Alder 20" dia., bears N.65°E., 67 lks. dist. mkd. T22S R10W S25 BT.
- The Maple 5" bears S.40°E., 63 lks. being destroyed, I mark
- A Fir 12" dia., bears S.71°E., 55 lks. dist. mkd. T22S R10W S36 BT.
- The Fir 5" bears S.42°W., 64 lks. being destroyed, I mark
- A Fir 16" dia., bears S.68°W., 82 lks. dist. mkd. T22S R10W S35 bT.
- A Maple 24" dia., bears N.30°W., 121 lks. dist. mkd. T22S R10W S26 BT.

BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #718, surveyed June/Aug 1970 - (DCSO records Vol. 36 Page(s) 14845)

The cor. of secs. 25, 26, 35 and 36, occupied with the remains of the original corner tree, a Fir snag, 40" dia., with fragmentary scribe marks visible on partially open blaze on SE., with healed blazes on the NE., SW., and NW. faces, from which the remaining original bearing trees:

- A sawed Fir stump 32" dia., bears S.61°W., 82 lks. dist. with healed blaze. (Rec. S.68°W.)
 - A sawed Maple stump 54" dia., bears N.38°W., 121 lks. dist. with healed blaze. (Rec. N.30°W.)
- from which reference monuments and bearing objects:
- An Iron post 28" long, 2½" dia., set 24" in the ground, for a reference monument, bears N.26½°E., 15 lks. dist. with brass cap mkd. T22S R10W S25 RM 1970 and an arrow pointing to the corner. (Cont. Next Page)

TOWNSHIP 22 RANGE 10 POINT IDENTIFIER # 600200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25, 26, 35 and 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A sandstone boulder, 30x20x15 ft. high, bears S.35¼°E., 166 lks. dist. mkd. X BO on N. face.
A sandstone boulder 6x5x5 ft. high, bears S.11 3/4°W., 54 lks. dist. mkd. X BO.
An iron post, 28" long, 2½" dia., set 24" in the ground, for a reference monument, bears N.57¼°W., 16½ lks. dist. with brass cap mkd. T22S R10W S26 RM 1970 and an arrow pointing to the corner.

Cor. Fd. OK, Sept. 1982 by E. Wobbe - M 93-14

BLM Dependent resurvey by Edith Forkner, Cadastral Surveyor, under Group #2750, surveyed April/May 2014 - (Plat T22-10-2016-1 all info on plat & DCSO records Vol. 58 Pgs 23319-20)

The cor of secs 25, 26, 35, & 36, monumented with the remains of the original cor. tree, a decayed fir stump, 32" dia, no marks visible, from which the remains of a bearing tree mkd. by Todd in 1894

A decayed fir stump, 23" dia, bears S.57¾°W., 54.1 ft., no marks visible. (Record, S.61°W.)

and the reference monuments mkd. by Jelley in 1970

An iron post, 2½" dia, firmly set, projecting 6" above ground, bears N.30°09'30"E, 9.90 ft., with a brass cap mkd. T22S R10W S25 RM 1970 and an arrow pointing to the cor. (Rec. N.26½°E.) A steel fence post is alongside.

An iron post, 2½" dia, firmly set, with top flush with the surface of the ground, bears N.59°55'37"W., 10.89 ft., with a brass cap mkd. T22S R10W S26 RM 1970 and an arrow pointing to the cor. (Record, N.57¼°W.)

At the corner point

Saw the cor. tree stump down to 6" above ground and drive an iron rod, 31" long, 5/8" dia., 30" in the center of the stump, with an aluminum cap mkd.

T 22 S R 10W

S 26 | S 25

S 35 | S 36

2014

from which new bearing trees

A fir, 14" dia, bears S.20¾°E., 99.8, mkd T22S R10W S36 BT

An alder, 14" dia, bears S.44°W., 48.0, mkd. T22S 10W S35 BT on bark.

The bearing objects mkd. by Jelley were recovered with no marks visible.

Drive an aluminum angle iron into the stump alongside the cor.