

PRIMARY CORNER DESCRIPTION Sec cor for 5, 6, 7 and 8

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #612, dated April 28, 1893 (DCSO records Vol. 5 Page(s) 1954)

Set a post 4 ft. long and 4' sq., 2 ft. in the ground for cor. to secs. 5, 6, 7 and 8, marked T22S S5 on NE.; R11W S8 on SE.; S7 on SW.; and S6 on NW. faces, with 5 notches on S. and E. edges, from which
A Fir 36" dia., bears N.56°E., 25 lks. dist. mkd. T22S R11W S5 BT.
A Fir 40" dia., bears S.46°E., 58 lks. dist. mkd. T22S R11W S8 BT.
A Maple 7" dia., bears S.56°W., 17 lks. dist. mkd. T22S R11W S7 BT.
A Fir 30" dia., bears N.7°W., 20 lks. dist. mkd. T22S R11W S6 BT.

Elliott State Forest Boundary Survey - L. Beyers and E. Lough 1939 or 1941 ? - (DCSO Field Book 123 Page 16)

Found bearing trees to corner and Set post 4"x4"x4 ft. from which
A Fir 40" dia., bears N.56°E., 16 ft. dist.
A Fir 48" dia., bears S.46°E., 38 ft. dist.
A Fir 36" dia., bears N.7°W., 13 ft. dist.
A Maple 12" dia., bears S.56°W., 12 ft. dist.

Survey by Warren D. Hootman - For: Cape Arago Lumber Co. - August 1958 - C.S. File 42/386 and M 12-47

Found all the original BTs:
BT in Sec. 7 is down and badly burned, no scribing visible but there has been a face on the tree.
BTs in Secs. 5 & 6 are healed over.
BT in Sec. 8 is a stump with an obvious face scar on the orig. bearing but 38.0 ft. dist. from the cor.
Point set from BTs in Secs. 5, 6 & 7.
Set a 1" x 36" galv. Pipe at the corner point.

Fd. OK, Jan. 1981 by R. Hintz - M 86-60

Gary T. Smither for Scott Timber Co. Jan. - April 1997 - M 124-51

Found - 2½" Brass cap set by Bureau Land Management in 1992.
49" Fir stump, N.56°W., 56 lks. with healed face.
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec cor for 5, 6, 7 and 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Found continued -
 35" Fir stump, N.7½°W., 18½ lks. with healed face.
 44" Fir stump, S.56°E., 57 lks. with healed face.
 35" Fir stump, N.7°W., 20 lks. with healed face.
 Note - Set 6 ft. steel post near monument.
 Note - as of 6/10/97 this office has not received the field notes of the BLM survey which set this Brass Cap.

Dependent resurvey by Boyd W. Peterson, Cadastral Surveyor, & Richard Sanford, Surveying Technician, under Group #1644, surveyed April 1992/May 1996. (DCSO rec. Vol. 53 Pg(s) 20225)

 The cor. of secs. 5, 6, 7, & 8, remonumented by Hootman, in 1958, and further recorded by Hintz, in 1980 and 1981; monumented with an iron pipe, 1" diam., firmly set, projecting 4" above ground, from which the remains of original bearing trees:
 A fir stump, 49" dia., bears N.56°E., 25 lks., with healed blaze.
 A fir stump, 44" dia., bears S.56°E., 58 lks., with healed blaze. (Record, S.46°E.)
 A fir stump, 35" dia., bears N.7°W., 20 lks., with healed blaze.
 and the remains of a bearing tree of unknown record
 A fir stump, 38" dia., bears N.61½°W., 52 lks., with healed blaze.
 At the corner point
 Set a stainless steel post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd.

T22S	R11W
S 6	S 5
S 7	S 8

1992

 No other suitable accessories available.
 Deposit iron pipe alongside and a white "DEEP-1" magnetic marker at base of stainless steel post.

Brent Bacon - For: Menasha Forest Products - 2/2005 - M147-32

 Found - 2½" pipe with 3¼" BLM brass cap marked: "T22S R11W S6 S5 S7 S8 1992"
 46" fir stump, N.56°E., 14.3' (record 16.5')
 43" fir stump, S.46°E., 38.1' healed face
 34" fir snag, N.7°W., 12.0' (record 13.2')
 New BTs- 8" fir, S.64°E., 12.7', scribed "T22R11S8BT"
 8" fir, S.33°W., 16.5', scribed "T22R11S7BT"
 9" fir, N.78°W., 19.5', scribed "T22R11S6BT"