

TOWNSHIP 22 RANGE 11 POINT IDENTIFIER # 240700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 5; & S 32, T21-11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 5 Page(s) 1858)

Set post for 1/4 sec. cor. No trees. Made trenches and mound as per instructions.

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #612, dated April 28, 1893 (DCSO records Vol. 3 Page(s) 1255 (duplicate Pg. 1895) and Page 1256 (duplicate Pg. 1895))

At 1/4 sec. point, I search for the 1/4 sec. cor. which is described as a post with trench and mound, but find no trace of same.
Re-established 1/4 sec. cor. at proportionate distance as follows:
Set a post 3 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor. marked 1/4 S. on N. face, dug pits, 18x18x12 ins. E. and W. of post, 5 1/2 ft. dist., and raised a mound of earth 1 1/2 ft. high, 3 1/2 ft. base alongside.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, John M. Powell and crew - July 9, 1971 - C.S. File 56/5-17 and M 42-27

This corner set from survey.
Set Brass cap at cor. mkd: County Surveyors Office
T21S R11W 1/4 S 32
T22S S 5
1971
Set steel fence post alongside brass cap.

Fd. OK, June 1987, Oregon State Hwy - C.S. File "0-1"

BLM Resurvey by Deborah M. Stephens and Harvey E. Wofford dated April 1990 thru April 1995 under group #1521. (DCSO records Vol. 51 Page(s) 19591)

The 1/4 sec. cor. of secs. 5 and 32, reestablished at proportionate measurement by Byron in 1971, accepted by Stuntzner in 1979, Hintz in 1980, and Peel in 1982. There is no remaining evidence of the original corner, therefore, this position is accepted as the corner. The Byron monument was removed during this survey by farm equipment after a traverse tie had been attained. The corner was reestablished from this traverse tie and the hole left by pipe.
(Cont. Next Page)

TOWNSHIP 22 RANGE 11 POINT IDENTIFIER # 240700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 5; & S. 32, T21-11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

At the corner point
Set a stainless steel post, 28 ins. long, 2½ ins. diam.,
28 ins. in the ground, the top flush with the ground surface,
with brass cap mkd.

T21S R11W
¼ $\frac{S\ 32}{S\ 5}$

T22S
1991

No suitable accessories available.
Set steel fence post alongside and deposit a white "DEEP-1"
magnetic marker at base of stainless steel post.

Fd. Ok on Dependent resurvey by Boyd W. Peterson, Cadastral
Surveyor, & Richard Sanford, Surveying Technician, under
Group #1644, surveyed April 1992/May 1996. (DCS0 records Vol.
53 Page(s) 20188)