

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3 & 4; 33 & 34 of T21-11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 5 Page(s) 1858)

-----  
Set post for the cor. to secs. 3, 4, 33 and 34, from which  
A Fir 6" dia., bears N.88°E., 86 lks. dist.  
A Willow 5" dia., bears S.42½°E., 45 lks. dist.  
A Maple 8" dia., bears S.66½°W., 116 lks. dist.  
A Fir 30" dia., bears N.21°W., 31 lks. dist.

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #612, dated April 28, 1893 (DCSO records Vol. 3 Page(s) 1254 (and duplicate page 1894 Vol. 5)

-----  
I found the cor. to secs. 3, 4, 33 and 34, which is a post 4" sq., marked T21S S34 on NE.; T22S S3 on SE.; R11W S4 on SW.; S33 on NW faces, with 3 notches on E. and W. edges, from which  
A Willow 8" dia., bears N.42½°E., 45 lks. dist. mkd. T22S R11W S3 BT.  
A Fir 30" dia., bears N.21°W., 31 lks. dist. mkd. T22S R11W S33 BT.  
The other bearing trees are gone.

Survey by Warren D. Hootman - For: Western Lane Logging Co. - July 1, 1959 - C.S. File 51/30 and M 15-23

-----  
Said point being witnessed by a 36" D.Fir which is the orig. BT. No trace of the Willow found in 1893.  
Set a sandstone rock, 20" x 21" x 9", and mark it with an "X" for the corner point and scribe new BTs as follows:  
D.Fir 33" DBH, bears N.42°15'E., 15.0 ft.  
Cherry 7" DBH, bears S.36°30'E., 10.5 ft.  
D.Fir 35" DBH, bears S.82°00'W., 58.5 ft.  
This corner lays on a N. slope facing the Umpqua River.

Survey by Ernesto Alvarado, U.S.F.S. (For DCSO) Crew: Carol Dickison and Colin Long - Oct. 2, 1981 - C.S. File 61/29-3

-----  
Found - 18" x 18" x 6" sandstone with "X" on top.  
34" D.Fir bears N.39°E., 14.3 ft. with healed face.  
47" D.Fir bears S.82°W., 57.7 ft. with healed face.  
SE Cherry BT is uprooted with part of scribing vis.  
43" D.Fir bears N.21°W., 20.5 ft. Face was chopped out approx. 48 years ago. All heartwood is rotten (powder). No scribing found. Traces of axe marks found. Tree has dead top. (Cut out, found the upper level part of blaze) (Cont. Next Page)

TOWNSHIP 22 RANGE 11 POINT IDENTIFIER # 400700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3 & 4; 33 & 34 of T21-11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Set 2½" Brass cap on 1" I.P, 30" long with flanged bottom, stamped "Douglas County Surveyors Office T21S R11W S33 S34 T22S R11W S4 S3 1981"

New BTs -6" D.Fir bears S.46°E., 25.2 ft. "X" scribed at breast height lower blaze scribed CS BT.

Location - Go East along Hwy. #38 approx. 4.6 miles from Reedsport to Alderwood Farm. Walk West on road So. side of creek (So. edge of pasture) approx. 600 ft. to location poster on Alder on South side of road. From poster, go S.10°W., 500 ft. to corner.

Fd. OK Feb. 1984 by James Prochnau - M 96-65 A & B and C.S. File 58/294 and M 96-64 A & B

Cor. Fd. and used in BLM resurvey by John Farmer Cadastral Surveyor, under Group #1421, surveyed Nov. 1987/Aug. 1994 (DCSO records, Vol. 51 pages 19283-84)

Fd. ok on Dependent resurvey by Boyd W. Peterson, Cadastral Surveyor, & Richard Sanford, Surveying Technician, under Group #1644, surveyed April 1992/May 1996. (DCSO records Vol. 53 Page(s) 20190)