

PRIMARY CORNER DESCRIPTION Sec. Cor. for 19, 20, 29 and 30

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 5 Page(s) 2005)

Set post corner of secs.19, 20, 29 and 30, from which
An Alder 15" dia., bears N.45°E., 2 lks. dist.
An Alder 12" dia., bears N.80°W., 95 lks. dist.
An Alder 12" dia., bears S.50°W., 14 lks. dist.
A Fir 24" dia., bears S.70°E., 30 lks. dist.

GLO survey by Simon B. Cathcart, Deputy Surveyor, under Contract #559, dated Nov. 15, 1890 - (DCSO records Vol. 5 Page(s) 2070)

The post has fallen down and is badly decayed. All marks being destroyed.

A Fir 30" dia., bears S.70°E., 30 lks. dist. with marks grown over.

An Alder 15" dia., bearing N.85°W., 90 lks. dist. still standing with marks distinct, T22S R12W S19 BT.

The Alder bearing N.45°E., 22 lks. dist. and the Alder bearing S.50°W., 14 lks. dist., are both down and so badly decayed that no marks could be found.

I set a Cedar post 4" sq. 4 ft. long, 2 ft. in ground with 2 notches on the South and 5 notches on the East edges marked T22S S20 on NE.; R12W S29 on SE.; S30 on SW. and S19 on NW. faces.

Survey by John Minor - For: Menasha Corp. - Nov. 1992 - M 116-11

Found - Down 36" D.Fir snag with orig. scribe visible.
Set 1" x 36" I.P. with 2" brass cap stamped "T22S R12W S19 S20 S29 S30 1992 LS 2052". BCIP set at record S.70°E., 19.8 ft. from face where it would have been if it were still standing.

New Accessories:

15" Alder N.60°E., 21.3 ft. barks scribed T22S R12W S20 BT.

30" Spruce S.39°W., 26.8 ft. scribed T22S R12W S30 BT.

31" Spruce S.48°E., 56.3 ft. scribed T22S R12W S29 BT.

18" Alder N.29°W., 5.6 ft. bark scribed T22S R12W S19 BT.