

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 16 and 17

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #534, dated Jan. 12, 1889 (DCSO records Vol. 5 Page(s) 2047)

-----  
Set a Cedar post 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S on W. face, from which

A Spruce 36" dia., bears N.86°W., 31 lks. dist. mkd. 1/4 S BT.

A Hemlock 10" dia., bears S.53°E., 36 lks. dist. mkd. 1/4 S BT.

Douglas County Surveyors Office - Janet Lundeen, Deputy - R. Smith and S. Flause, Crew -April 31, 1986 - C.S. 62/43-E and M 101-18

-----  
Found - Orig. 10" Hemlock, fallen and out of position, now 16" with scribing "BT". Partial root wad still visible and in position, bears S.53°E., 23.8 ft. (rec.) Base of fallen tree bears N.9°E., 8 ft., from root wad.

Orig. 36" Spruce, now 48" rotted stump 5 ft. high, with partially rotted blaze, no scribing found, bears N.86°W., 20.5 ft. (Rec.)

As the location of the fallen Hemlock was obvious, we determine a position by intersecting distances. This position agreed with record bearings.

Set a 2 3/8" brass cap on 1" (1 3/8" O.D.) x 32" pipe marked:  
Douglas County Surveyors Office

T 22 S  
S 17 | S 16  
R 12 W  
1986

New BTs -12" Spruce bears N.54 1/4°E., 33.6 ft. scribed "1/4 S16 CS BT" in double blaze.

18" D.Fir bears S.56 1/2°E., 20.0 ft. scribed "1/4 S16 CS BT" in double blaze.

14" D.Fir bears S.43 1/4°W., 18.9 ft. scribed "1/4 S17 CS BT" in double blaze.

18" Hemlock bears S.83 3/4°W., 37.8 ft. scribed "1/4 S17 CS BT" in double blaze.

The orig. line notes topog. call to South fit well but the call to the North misses by 180 ft. ±.