

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 16 and 21

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #534, dated Jan. 12, 1889 (DCSO records Vol. 5 Page(s) 2049)

-----  
Set an Elder post 3 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor. mkd. 1/4 S on N. face, from which

A Spruce 48" dia., bears S.20°E., 62 lks. dist. mkd. 1/4 S BT.

A Spruce 54" dia., bears N.15°E., 42 lks. dist. mkd. 1/4 S BT.

This post stands in a shallow gulch, course North.

-----  
Survey by Harvey Wilcox - For: I.P. Timberlands - March 1992 - M 115-4

Found - Rotten Spruce stump bears S.20°E., 40.9 ft. to face. (Orig. BT.)

Rotten Spruce stump bears N.15°E., 27.7 ft. to face. (Orig. BT)

Set 3 1/4" alum. cap on 3/4" x 36" alum. rod. Cap is marked "I.P. Timberlands Operating Co. RLS 2244 T22S R12W 1/4 S16 S21 1992". Cap set in shallow gulch.

New BTs -35" Cedar, face scribed "1/4 S16 BT" with "X" and tags, bears N.01°E., 35.8 ft.

16" Fir, face scribed "1/4 S16 BT" with "X" and tags, bears N.61°E., 48.3 ft.

10" Alder, bark scribed "1/4 S21 BT" with "X" and tags, bears S.50°E., 22.3 ft.

12" Spruce, face scribed "1/4 S21 BT" with "X" and tags, bears S.39°W., 6.2 ft.

-----  
John Minor, L.S. #2052 - For: Menasha Corp., Moore Mill, & Douglas County -November 1994 - M 121-32

CONDITION REPORT ONLY

Found - 3 1/4" aluminum cap on 3/4" aluminum rod, 3" above ground w/I.P. Timber Lands Operating Co. markings.

36" Cedar N.2°E., 35.7 ft. (M 115-4) Vis. scribe.

66" Spruce stump, N.15°E., 28.7 ft. to center (Orig. M 115-4 27.7 ft. to face)

16" D.Fir, N.62°E., 48.3 ft. (M 115-4, N. 61°E.)

11" Alder, S.49°E., 22.4 ft. (M 115-4, S.50°E., 22.3) B.S.

Rotten Spruce stump S.20°E., 40.9' .(Orig.) to face.

13" Spruce S.40°W., 6.1 ft. (M 115-4, S.39°W., 6.2') Vis. scribe.

Fence post w/monument sign bears East 1.5 ft.