

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #534, dated Jan. 12, 1889 (DCSO records Vol. 5 Page(s) 2036)

Set a Cedar post 3 ft. long, 3" sq., 24" in the ground, for 1/4 sec. corner mkd. 1/4 S on N. face, from which

A Hemlock 12" dia., bears N.59°W., 37 lks. dist. mkd. 1/4 S BT.

A Spruce 30" dia., bears S.60°E., 39 lks. dist. mkd. 1/4 S BT.

Survey by Ronald Stuntzner - For: Douglas County Land Dept. - April 18, 1985 - M 98-54

Found - 12" Hemlock now 34" uprooted, face bears N.54°W., 23.5 ft. (Rec. N.59°W., 37 lks.) Opened face and found visible "BT" scribes.

30" Spruce now 64" stump remains., S.60°E., 25.7 ft. (39 lks.)

Set 2" x 30" I.P. with 2" alum. cap mkd. "T22S R12W 1/4 S9 S16 1985 LS 1342", from which

New BTs -23" D.Fir bears N.89°E., 19.5 ft. scribed 1/4 S9 BT.

17" D.Fir bears S.28°W., 12.0 ft. scribed 1/4 S16 BT., faced and painted.

Survey by W. Carey Weatherly LS 1667 - For: International Paper Co. - Nov/Dec. 1991 - C.S. File 63/129

Found - 30" downed Hemlock N.60°W., 25.5 ft. Orig. BT. (Rec. N.59°W., 24.42 lks.)

Set 3/4" x 12" alum. rod with 5" alum. tip and 3 1/4" alum. cap 12" below gravel surface of logging road in ditch line on northerly side of road. Buried orange magnetic marker next to monument.

New Accessories:

18" W.Red Cedar bears N.49 1/4°W., 52.9 ft. to spike in side. (dead)

24" burned W.Red Cedar stump 12 ft. high, bears S.81 1/2°E., 50.4 ft. to spike in side.

17" burned D.Fir stump 12 ft. high bears S.41°E., 36.3 ft. to spike in side.

27" D.Fir stump 1 ft. high bears S.0 1/4°E., 35.6 ft. to spike in side.

6 ft. alum. post with survey monument sign and IP Co. location tag, bears North 7.0 ft.

Monument and 2 BTs set by Stuntzner in 1985 and Spruce stump, orig. BT, destroyed during road construction. Prior to road construction, 3 reference points were set.