

TOWNSHIP 22 RANGE 12 POINT IDENTIFIER # 400640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 5 Page(s) 1997)

Set ¼ sec. post, from which
 A Hemlock 18" dia., bears N.67°E., 19 lks. dist.
 A Hemlock 30" dia., bears S.68°W., 15 lks. dist.

Fd. 2" I.P., Feb. 14, 1966, R. Hintz - C.S. File 51/335-2

Fd. 1½" Iron pin set in 6" dia. concrete cylinder. Monument lies approx. 6" below surface and is located next to the SE cor. of cement footing fo fence. - Feb. 1975 - C.S. File 59/46-70

Survey by Richard Hintz - For: International Paper Co. - March 1987 - M 103-59

Corner Report Only
Found 1 1/8" Iron rod set in concrete on the South line of Highlands Addition to the City of Reedsport.
Origin unknown but accepted as the best available evidence of the position of the original corner.

Fd. OK, Sept. 1993 - M 117-64
Fd. Ok M. Schulze, 5/2009 - M159-25