

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3 & 4 only, T23-12

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #341, dated October 4, 1879 (DCSO records Vol. 5 Page(s) 2021)

Set Fir post 5x5 by 4 ft. long in ground for corner to Secs. 33, 34, 3 and 4, from which
A Fir 18" dia., bears N.43°E., 50 lks. dist.
A Cherry 8" dia., bears S.85°E., 48 lks. dist.
A Myrtle 6" dia., bears S.35°W., 28 lks. dist.
A Fir 12" dia., bears N.50°W., 45 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #534, dated Jan. 12, 1889 (DCSO records Vol. 5 Page(s) 2045)

Cor. to secs. 3 and 4, which is a post, 5" sq., 24" above ground marked S34 on NE.; S3 T23S on SE.; S4 R12W on SW.; S33 on NW. faces, from which
A Fir 18" dia., bears N.43°E., 50 lks. dist. mkd. S34 T22S R12W BT.
A Cherry 8" dia., bears S.85°E., 48 lks. dist. mkd. S3 T23S R12W BT.
A Myrtle 6" dia., bears S.35°W., 28 lks. dist. mkd. S4 T23S R12W BT.
A Fir 12" dia., bears N.50°W., 45 lks. dist. mkd. S33 T23S R12W BT.

I destroyed marks referring to S33 on post and bearing trees, (NB. In accordance with the description given in the field notes furnished me.)

Survey by Jean Ewen, Registered Engineer, - For: Erickson, et al - July 14, 1957 - C.S. File 58/37

Corner Report only
A 3"x3" post, identified and accepted by the adjacent property owners, reported to have been established in 1946, and from which post a
40" blazed stump, no identifiable marks, bears N.43°E., 30.5 ft.
18" Fir blazed and with a BLM metal corner marker bears S.50°W., 34 ft.
The area having been logged off, no other identifiable marks or evidence of original lines could be found.

Fd. I.P. and three original bearing trees, 1959 by W. Hootman - C.S. File 51/55 and 58/37

(Cont. Next Page)

TOWNSHIP 22 RANGE 12 POINT IDENTIFIER # 412100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3 & 4 only, T23-12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Survey by Ronald E. Stuntzner - Nov. 14, 1970 - C.S. File 55/172

Found 3/4" Iron pipe for sec. corner, from which
30" White Fir stump with tag, N.41°E., 33.0 ft.
Myrtle clump S.35°W., 17.8 ft.

I Scribed:
26" Fir N.80°W., 14.9 ft.
50" White Fir N.50°W., 20.6 ft.

Fd. OK Jan. 1986 by Lloyd D. Smith, OSBF - M 100-37

Survey by Mark Hoyer, LS #2098 - For: Menasha Corp. - Nov. 1987 - C.S. File 63/65 and M 105-15

Found - 3/4" Iron pipe.
Myrtle clump, S.35°W., 17.8 ft., rotten face.
30" W.Fir stump N.41°E., 33.0 ft., rotten.
26" D.Fir stump N.80°W., 14.9 ft., face visible.
50" W.Fir stump N.50°W., 20.6 ft., face visible.

I remonument by driving a 1½" x 36" I.P. with brass cap over existing pipe and tag the four bearing trees.