

PRIMARY CORNER DESCRIPTION NE 1/16th Sec. 27

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Mark Hoye - For: Menasha Corp - June 1987 - M104-31

Set - 1½"x36" IP with brass cap
38" Cedar, N.71°E., 11.3'
50" Cedar, S.58°E., 25.8'
BTs are scribed & tagged measurements to spike in base.

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike
- Sept. 1, 2005 - C.S. File 67/13-1

Found - IP with brass cap set by Hoye in M104-31 missing.
Spur road and landing construction has removed 2+
ft. of ridge-top soil surface.
From Hoye's survey a 50" Cedar, now a 51" DBH 9 ft.
tall cedar stump with a partially healed blaze,
scribed "1/16". A large spike nail is driven in
low on NW face of this stump.

Set - From the head of the spike nail in the fd. Cedar BT
stump we measure N.58°W., 25.8 ft. (as per rec.)
and set a 2 3/8" dia., brass cap (marked DOUGLAS
CO. SURVEYORS OFFICE NE1/16 + 2005) on a 1½" O.D.
x 32" long iron pipe. Monument is set with brass
cap flush with ground.

A 5 ft. white metal fence post is set as a guard
stake protruding 4 ft. above ground and approx.
1 ft. north of BC.

A 5" DBH Red Alder bark scribed (through cambium
layer) "NE 1/16" S27 CS BT" bears N.23°E. 13.7 ft

An 8" bridge spike stamped "B01" on top set
protruding approx. 1" above the surface & plumb
over the center of the root crown of a 32" dia.,
2½ ft. tall stump bears S.28°W., 44.8 ft.

A 7" DBH D.Fir scribed "NE 1/16 S27 CS BT" on a
double blaze bears N.32°W., 42.6 ft.

Note - Monument is on westerly edge of small landing on
unused & over-grown spur road following near top
of small ridge running NNW-SSE.

Compass decl. 16¾°E.