

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 14

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 5 Page(s) 1996)</p> <p>-----</p> <p>Set ¼ sec. post, from which</p> <ul style="list-style-type: none">A Spruce 18" dia., bears S.27°E., 54 lks. dist.A Fir 50" dia., bears N.3°E., 47 lks. dist.
<p>Survey by Warren D. Hootman - For: Cape Arago Lumber Co. - Sept. 10, 1957 - C.S. File 42/305</p> <p>-----</p> <p>I find the stump of the original BT for Sec. 11. (N.3°E., 31.0 ft.) Part of the scribing is still visible. The stump in Sec. 14 is gone and its position is in a cat road. I set a 1" x 36" galv. I.P. at the call distance from the original bearing tree stump.</p> <p>Marked two new bearing trees as follows:</p> <ul style="list-style-type: none">D.Fir 10" DBH, bears S.36°30'W. 107.5 ft. dist.Hemlock 4" DBH, bears N.78°30'E., 40.2 ft. dist.
<p>Survey by Clifford A. Stephens - For: J. Lightfoot - May/June 1965 - C.S. File 51/321 and M 22-72</p> <p>-----</p> <p>Find 1" Iron pipe for the ¼ corner and one orig. BT stump, from which new BTs:</p> <ul style="list-style-type: none">10" Fir bears S.36°30'W., 107.5 ft. (1957)4" Hemlock bears N.78°30'E., 40.2 ft. (orig. BT)
<p>Survey by B.W. Holt - For: Sun Studs, Inc. - Oct. 1984 - C.S. File 58/298 and M 97-63</p> <p>-----</p> <p>Corner Report</p> <p>Found 3/4" Iron pipe, from which</p> <ul style="list-style-type: none">A 44" D.Fir stump, rotted, bears S.41°E., 5.4 ft., no scribing.A 14" Spruce snag, 6 ft. high bears N.70°W., 9.2 ft., no scribing.A 22" D.Fir bears S.36°30'W., 107.6 ft., healed face.A 15" Hemlock bears N.63°E., 33.2 ft., healed face.A 16" Hemlock bears S.70°E., 40.2 ft., healed face. <p>Corner lies on shallow ridge, 15 ft. North, old road.</p>
<p>1</p>