

PRIMARY CORNER DESCRIPTION E. 1/4 Corner for Sec. 23 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #323, dated May 26, 1879, - (DCSO records Vol. 5 Page(s) 2016-17)

Set Chittenwood post 4 ft. long 5" dia., 20" in ground for the ¼ sec.cor. bet. secs. 23 and 24, from which
A Fir 8" dia., bears N.32°E., 20 lks. dist.
A Fir 36" dia., bears S.30°W., 29 lks. dist.

GLO survey by Charles A. Slang, Deputy Surveyor, under Contract #793, dated Feb. 17, 1910 - (DCSO records Vol. 5 Page(s) 2096 and 2098)

(Page 2096)
Point for old ¼ sec. cor. as determined by old overgrown marks on a down tree; other witness tree gone entirely and no post could be found.
(Page 2098)
At point for old ¼ sec. cor., I destroy all trace of this old cor. and reestablish at the same point as follows:
Set a sandstone 15x12x10 ins., 10" in the ground for ¼ sec. cor. mkd. ¼ on W. face, from which
A Fir 15" dia., bears S.61°W., 57 lks. dist. mkd. ¼ S23 BT.
A Fir 15" dia., bears S.60°W., 40 lks. dist. mkd. ¼ S23 BT.

Survey by Arnold G. Gibson - For: Oregon State Board of Forestry - June 23, 1971 - M 44-33

Set OSBF 1½" x 36" I.P. with 3" bronze cap, 34" in ground, from which
9" Cedar N.68½°W., 19.1 ft. with yellow metal location poster.
18" Cedar S.30°W., 33.6 ft. "RS 359".
4"x4"x72" white painted cedar post N.60°W., 2.0 ft.

Survey by Bruce A. Shaner - For: Moore Mill & Lumber Co. - Feb. 1987 - RM 3-66 A & B

Found - 3" brass cap on a 2"x40" iron pipe mkd. OSBF ¼ S23 1971 S-359.
10" Cedar bears N.68½°W., 19.1 ft.
22" Cedar bears S.30°W., 33.6 ft.

(Cont. Next Page)

TOWNSHIP 22 RANGE 12 POINT IDENTIFIER # 600340

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 23 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

The quarter sec. cor. to sec. 23 only was erroneously set by the OSBF in their 1972 survey. Since this was set way out of position by the OSBF, I removed the brass cap and I.P. and placed a 5/8" x 36" I. Rod in its place. Tags were removed from the bearing trees and cedar post was removed.

I reestablished the quarter sec. cor. to sec. 23 only by proportionate measurement as recorded by the OSBF in their 1972 survey.

Set a 2½" brass cap on a 2" x 34" iron pipe set 32" in the ground mkd. "¼S S23 RLS 430 1987".

BTs - A 48" D.Fir bears N.41°W., 38.5 ft. scribed ¼S S23 BT
A 44" D.Fir bears S.41°W., 56.2 ft. scribed ¼ S23 BT.

Fd. OK, May 1991 - M 113-35 A&B