

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 5 Page(s) 2127)

Set a Fir post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. corner mkd. ¼ S on W. face, from which
A Fir 18" dia., bears S.87°W., 23 lks. dist. mkd. ¼ S BT.
A Cedar 24" dia., bears East 58 lks. dist. mkd. ¼ S BT.

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 5 Page(s) 2129 and 2130)

I am unable to find the ¼ sec. cor.
Set basalt stone 18x8x6 ins., 14" in the ground for ¼ sec. cor. mkd. ¼ on W. face, from which
A Cedar 18" dia., bears S.18°E., 50 lks. dist. mkd. ¼ S BT
A Fir 24" dia., bears N.61°W., 25 lks. dist. mkd. ¼ S BT.

BLM resurvey by Wm. W. Glenn and Harvey E. Wofford, Cadastral Surveyors, under Group #345, Surveyed Sept. 1964/July 1966 - (DCSO records Vol. 35 Page(s) 14305-06)

(35.97 chs.)
A Corner established by McQuinn in 1883, bears East, 0.418 chs. dist., determined from the original bearing trees:
A Cedar 34" dia., bears East 61 lks. dist., with healed blaze. (Rec. and dist. to face, 58 lks.)
A Fir snag 28" dia., bears S.87°W., 25 lks. dist. with scribe marks ¼ S visible on bark blaze. (Rec. and dist. to face, 23 lks.)
This corner was superceded by Chandler's survey.
(39.55 chs.)
Point for the ¼ sec. cor. of secs. 31 and 36, at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post 28" long, 2½" dia., 24" in the ground with brass cap mkd.
T 23 S
R 2 W ¼ R 1 W
S 36 | S 31
1964
from which
A Fir 48" dia., bears S.44½°E., 31 lks. dist. mkd. ¼ S31 BT.
A Fir 36" dia., bears S.53°W., 78 lks. dist. mkd. ¼ S36 BT.

(Cont. Next Page)

TOWNSHIP 23 RANGE 01 POINT IDENTIFIER # 100140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 31; & 36, T23-2

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Fd. OK, March 1973 by Nick Juliano - C.S. File 58/24

Glen McChesney - For: Weyerhaeuser Co. - March 10, 1978
(Filed Dec. 1980) C.S. File 58/8-3

Found - 1964 GLO brass cap.
Down, windthrown 36" Fir, slid down hill; plate
intact, face partly healed, bears S.44°E., 20.5
ft. to center of root hole.
32" Fir, low face healed over; BLM BT plate intact,
bears S.55°W., 51.7 ft. to center of tree
measurement.

Accessories Added:

40" Fir N.69°E., 8.3 ft.
18" Hemlock S.61°W., 3.8 ft.
32" Red Cedar stump, bears N.78°W., 50.8 ft.
Trees have "W" nail with Weyerhaeuser plate.

David Wellman - For: Weyerhaeuser Co. - 7/8/2004 - C.S. File
65/52-3 A&B

Found - 2½"x28" iron pipe with BLM BC dated 1964, 0.5 AGL
40" Fir snag, WEYCO tag reads S.69°W., 8.3 ft." to
"W" nail.
18" Hemlock stump, WEYCO tag reads "N.61°E. 50.8 ft"
to "W" nail - rotten.
32" R.Cedar stump, WEYCO tag reads "S.78°E. 50.8 ft"
to "W" nail.
New - 10" Cedar, S.13½°E., 21.7 ft. to spike set side
center - scribed "W¼ S31 BT"