

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 33

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619 dated June 5, 1893 - (DCSO records Vol. 5 Page(s) 2202)

-----  
Set a basalt stone, 12x10x8 ins., 9 ins., in the ground for 1/4 sec. cor., mkd: 1/4 on N. face; from which  
A Cedar, 24" dia., bears N.81°E., 9 lks., mkd: 1/4 S BT.  
A Cedar, 18" dia., bears S.20°E., 16 lks., mkd: 1/4 S BT.

-----  
Glen McChesney under supervision of Frank O. Williams - For: Weyerhaeuser - June 1976, Dec. 1976 & July 1982 - C.S. 62/1-26

-----  
June 1976  
Found - Orig. stone & scribing visible on 2 OBTs.  
Referenced with W nails & plates on -  
54" R.Cedar S.81°E., 155.1 ft.  
60" Fir S.48°E., 75.3 ft.  
56" Fir N.46 3/4°W., 99.6 ft.  
Dec. 1976  
Orig. stone & BTs destroyed by road construction.  
1976 SE BT (R.Cedar) destroyed by road construction.  
1976 SE BT (Fir) intact.  
1976 NW BT (Fir) now a stump, was notched for a guyline stump & W nail was sawn out when notched. I found segment with W nail on ground & fitted this segment back into its orig. position & renewed plate with same bearing & distance. I also drove W nail in the approx. center of this stump N.46 3/4°W., 3.0 ft. from the replaced W nail therefore making the distance between the W nail & the corner point 102.6' Point in road determined by Bearings & distances from 6/1976 referenced trees. Nothing set.  
July 1982  
Added 56" Fir snag stump S.20°E., 40.7 ft. with nail & Weyerhaeuser Tag.  
60" Fir at S.48°E., 75.3 ft. is down & out of place.

-----  
Fd. by Donald Peel 8/1982 - M 92-78

-----  
Douglas Co. Surveyors Office - Gregory Quibell, Deputy - Karen Reed - Terrie Plouff - C.S. 62/1-26 - Oct. 20, 1982

-----  
Found - Hub & tack in center of logging road as per M 92-78. All orig. evidence has been destroyed by road construction, however the corner has been perpetuated by Weyerhaeuser June 1, 1976 and again Dec. 12, 1981 & July 27, 1982.  
56" Fir per Weyerhaeuser, now 73" Fir stump bears N.46 3/4°W., 102.6 ft. to "W" nail near center of stump, as per rec.  
56" Fir per Weyerhaeuser, now 73" Fir stump bears N.46 3/4°W., 102.6 ft. to "W" nail near center of stump, as per rec.

continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 33

Alias	Description

56" Fir snag per Weyerhaeuser, now 65" stump bears S.20°E., 40.7 ft. to "W" nail in face as per rec.  
24" Cedar stump per Weyerhaeuser, bears N.88½°E., 69.6 ft. (Rec. East) to "W" nail in face.  
60" Fir at S.48°E., 75.2 ft. is down & out of place, as per Weyerhaeuser.

Set - Since corner fell in rock road, I set a 1"x30" iron pipe with brass cap attached, North 40.0 ft. for witness corner. Cap mkd: Douglas Co. Surveyor Wit Cor 40 ft South to T23S ¼ S28 S33 R2W 1982.

New BTs- 17" Cedar scribed "X CS BT" in double blaze bears S.55½°E., 175.9 ft.  
22" Fir scribed "X CS BT" in double blaze bears S.31°W., 292.4 ft.

DCSO BT tags on all trees.

---

Russell Badgley - For: Weyerhaeuser Co. - 7/2020 - M177-22  
-----

Found - A 1½" iron post by DCSO in 1982 as a 40 ft witness corner, firmly set and projecting 8" above the ground, with a 2½" brass cap (properly) marked. From which bearing trees by DCSO in 1982  
A 17" Cedar stump bears S.55°00'E., 175.6 ft [S.55°30'E., 175.9']  
A 22" D.Fir snag bears record [S.31°W., 292.4'] could not see from wit. corner

New - At the true corner location I set a 5/8"x30" iron rod, 2" below the road surface, with a 2" aluminum cap stamped  
BTS SURVEYING INC  
T23S R2W  
¼ S28  
S33  
2020  
PLS 70716

From which BTs by McChesney in 1976-1982 per C.S. 62/1-26:  
A 73" Fir stump bears record [N.46¾°W., 102 6'] per DCSO in 1982 could not see from corner  
A 65" D.fir stump bears S.20°54'E., 44.25 ft to mag hub in center [S.20°E., 40.7' to nail in face]  
A 24" Cedar stump bears N.88°32'28"E., 69.60 ft to 'W' Nail in face [N.88½°E., 69.6'] held

New BTs- A 17" D.Fir bears N.15°00'E., 46.1 ft scribed "¼ S28 BT" on dbl blaze  
A 14" D.Fir bears N.33°30'W., 25.5 ft scribed "¼ on dbl blaze

Note - Corner falls in old logging road no longer in use.