

TOWNSHIP 23 RANGE 02 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 25 & 26

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

<p>New BTs- 42" Fir bears S.68°E. 6.3 ft. with "W" nail & plate. 58" Fir stump bears S.23°W., 23.1 ft. with "W" nail & plate.</p>
<p>Dan Baker - For: Weyerhaeuser Co. - 9/30/2011 - C.S. 65/76-2 ----- Found - 2½" Douglas County brass cap "1969" 14" Hemlock N.42°E. 19.6' - Douglas County BT 48" rotten fir stub N.64°E. 5.3' - original 58" Fir stump. S.23°W. 23.1' to "W" nail 13" hemlock snag S.41°W. 49.4' Douglas County BT 40" fir snag, S.75°W. 13.3' - original New - 9" Hemlock, S.10°W., 18.3' to spike in side-scribed "¼ S26 BT"</p>
<p>Dan Baker - For: Weyerhaeuser Co. - 11/2021 - M180-19 ----- Condition report Found - 2½" Douglas Co. brass cap "1969" 14" hemlock, N.42°E., 19.6' to side/center-1969 48" rotten fir stub, N.64°E., 5.3' to center OBT 58" fir stump, S.23°W., 23.1' TO "W" nail 13" hemlock snag, S.41°W., 49.4' to side/center 40" fir snag, S75°W, 13.3' to center OBT 13" hemlock, S.10°W., 18.3' to spike side/center</p>
<p>Please note that this corner is on the Douglas Co. & Lane Co. line and Lane Co. Surveyor's Office may have more information concerning this corner.</p>
<p> </p>