

TOWNSHIP 23 RANGE 03 POINT IDENTIFIER # 104100

PRIMARY CORNER DESCRIPTION C C for Sec. 6, T24-3; and S. 1, T24-4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO records Vol. 7 Page(s) 2969)

At point of intersection, Set a Cedar post 4 ft. long, 4" sq., 24" in the ground for closing cor. to Tsp. 24 S., Rs. 3 and 4 W. marked CC T24S on S.; R3W S6 on E. and R4W S1 on W. faces, with 6 notches on S., E. and W. faces, from which
A Fir 10" dia, N.22°E., 10 lks. dist. mkd. T23S R3W S31 BT
A Dogwood 5" dia., bears S.16°E., 79 lks. dist. mkd. T24S R3W S6 BT.
A Fir 7" dia., bears S.38°W., 118 lks. mkd. T24S R4W S1 BT

GL0 survey by Oscar F. Thiel, Deputy Surveyor, under Contract #658 dated May 21, 1896 (DCSO records Vol. 7 Page(s) 3079)

Fires have repeatedly been through here and no sign of post or its small bearing trees remain.

BLM Resurvey by Norman D. Price, Cadastral Engineer, under Group #242, Surveyed June/Aug. 1950 - (DCSO records Vol. 27 Page(s) 11471)

Point for the closing cor. of Tps. 24 S., Rs. 3 and 4 W., at proportionate distance on the S. bdy. of sec. 31, T23S R3W., there is no remaining evidence of the original corner.
Set an iron post 3 ft. long, 3" dia., 30" in the ground, with brass cap mkd.
T 23 S R 3 W
S 31

S 1 | S 6
R 4 W | R 3 W
T 24 S
C C
1950

from which
A Fir 9" dia., bears S.48°E., 65 lks. dist. mkd. T24S R3W S6 CC BT.
A Cedar 7" dia., bears S.43¼°W., 82 lks. dist. mkd. T24S R4W S1 CC BT.
This closing corner is located on a small spur, slopes E.

Marion D. Hale, Weyerhaeuser Co - Nov. 1961 - C.S. 51/31-2

Corner Report
Found - Brass cap
9" Fir S.48°E., 65 lks.
7" Cedar S.43¼°W., 82 lks.

(Cont. Next Page)

TOWNSHIP 23 RANGE 03 POINT IDENTIFIER # 104100

PRIMARY CORNER DESCRIPTION C C for Sec. 6, T24-3; and S. 1, T24-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Bruce Malcom - For: Weyerhaeuser Co. - 1962 - C.S. File 53/111-13

Found - Iron post and brass cap visible.
9" Fir S.48°E., 65 lks., is still standing but a snag. Scribing is still visible.
7" Cedar S.43¼°W., 82 lks.; has been knocked down by logging, is now a 10" snag, 6 ft. high, scribing is still legible but is partially torn from stump.

Accessories added this date:

19" Fir N.7°E., 20.6 ft. with "W" nail and plate.
8" Fir N.62°E., 35.8 ft. with "W" nail and plate.
12" Fir S.59°E., 34.6 ft. with "W" nail and plate.
12" Cedar S.53°W., 12.3 ft. with "W" nail and plate.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy; M. Stone - July 1963 - C.S. File 53/9-114

Found - Brass cap set by Price in 1950.
9" Fir snag S.48°E., 42.9 ft., all scribing visible on open face.
7" short Cedar snag S.43¼°W., 54.1 ft., all scribing visible on open face.

New BTs- 10" D.Fir S.58°E., 28.2 ft. mkd. T24S R3W S6 CC CSBT
13" Red Cedar S.54½°W., 47.9 ft. mkd. T24S R4W S1 CC CS BT.