

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 29

Alias	Description

GLO survey by James P. Currin, Deputy Surveyor, under contract #438, dated May 3, 1882 - (DCSO records Vol. 6 Page(s) 2246)

-----

Set a post 3 ft. long 4" sq. 20" in the ground for ¼ sec. cor. mkd: ¼ on W face from which  
A Hemlock, 24" dia., bears S.40°W., 50 lks., mkd: ¼ S BT.  
A Fir, 24" dia., bears N.10°E., 75 lks., mkd: ¼ S BT.

Marion D. Hale - Wit: H.E. Case & W.W. Dixon - For: Weyerhaeuser Timber Co. - Filed June 19, 1959 - C.S. File 51/25, C.S. 53/1-30 & C.S. File 53/107-7

-----

Found - GLO survey rec., Post, gone  
24" Hemlock S.40°W., 50 lks., fd.: 334" Hemlock stump with part of old face. Partially destroyed by logging.  
24" Fir N.10°E., 75 lks., fd: 54"x30' high Fir snag with BLM plate.

Set - ½"x34" galv. iron pipe for corner from the above 34" Hemlock stump using rec. bearing & dist.

Referenced by Hale (plate & "W" nails only) Decl. 20°  
39" Hemlock stump S.70°E., 65.5 ft.  
30" Cedar stump N.75°W., 43.6 ft.

Fd OK by Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Oct. 1967 - C.S. File 54/16-25A

David Wellman, for Weyerhaeuser Co. Jan. 8, 1998 - C.S. File 65/20-3

-----

Found - ½" x 34" galv. iron pipe. 1959  
30" Cedar stump, N.75°W., 43.6 ft. to "W" nail  
39" Hemlock stump, S.70°E., 65.5 ft. to "W" nail  
BLM tag, 54" x 30 ft. Fir snag, N.10°E., 60 ft. slope dist. to corner.

Set - 1½" x 30" iron pipe with 2½" cap dated 1998  
14" Fir, N.66°E, 23.7 ft to "W" nail/scribed ¼ S28  
18" Fir, S.33°E. 5.7 ft. to "W" nail/scribed ¼ S28  
17" Fir S.47½°W. 15.8 ft to "W" nail/scribed ¼ S29  
20" Fir N.43½°W. 29.1 ft to "W" nail/scribed ¼ S29

Note - Corner lies in slight depression on easterly side of wide ridge. Road switchback and landing bears N.65°W about 300 ft. distant.

Please note that this corner is on the Douglas Co. & Lane Co. line and Lane Co. Surveyor's Office may have more information concerning this corner.