

TOWNSHIP 23 RANGE 03 POINT IDENTIFIER # 440100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 34; & 3, T24-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by James P. Currin, Deputy Surveyor, under Contract #438, dated May 2, 1882 - (DCSO records Vol. 5 Page(s) 2214)

Set post 3 ft. long, 3" sq., 20" in the ground for 1/4 sec. cor. mkd. 1/4 S. on N. face, from which

A Yew 7" dia., bears N.40°W., 15 lks. dist. mkd. 1/4 S BT.

A Dogwood 6" dia., bears N.75°E., 20 lks. dist. mkd. 1/4 S BT.

Cor. on S. hill side in brush.

Weyerhaeuser Co. - 1958 - C.S. File 53/107-13

Found - Orig. post gone, cruiser's marks.

Orig. 7" Yew, N.40°W., 9.9 ft., no leaning, scribe partially visible.

No trace of 6" Dogwood, N.75°E., 13.2 ft.

Set 3/4" x 31" monel pipe, (1958)

BTs - 48" Fir S.53°W., 54.7 ft. "W" nail and plate.

36" Cedar N.30°E., 49.0 ft. "W" nail and plate.

7" Yew (June 1941) N.40°W., 9.9 ft. (Orig. BT) "W" nail and plate.

Douglas Co. Surveyors Office - V.R.T. - Oct. 1967 - C.S. File 54/16-26

NOT FOUND. Destroyed by recent logging and road construction.