

TOWNSHIP 23 RANGE 03 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by James P. Currin, Deputy Surveyor, under contract #438, dated May 3, 1882 - (DCSO records Vol. 6 Page(s) 2238)

Set a post 3 ft. long 4" sq. 20" in the ground for ¼ sec. cor. mkd: ¼ on N face from which
A Fir, 24" dia., bears S.45°E., 25 lks., mkd: ¼ S BT.
A Fir, 36" dia., bears N.45°E., 4 lks., mkd: ¼ S BT.

Weyerhaeuser Co. 1957 thru 1963 C.S. File 53/107-18 (March 1957)

Found - Post gone at intersection of E-W & N-S cutting line blazes.
Fd. 1914-16 blazes, cruiser mark "W" on piece Fir bark knocked off of 50" Fir stump, also BLM plate on this piece of bark mkd. S.45°W., 29 ft. on slope to S ¼ cor. secs. 27-23S-3W.
Cruiser mark "LF" on down 14" maple.
(orig.) 24" Fir S.45°E., 25 lks., found a 36" Fir stump S.47½°E., 15.5 ft. fits close to evidence, no axe or scribing fd., probably rubbed off.
36" Fir N.45°E., 4 lks., gone, cat road at this position.
BTs - 36" Fir stump (assumed orig. BT) S.47½°E., 15.5 ft. "W" nail & plate.
50" Fir stump N.57½°E., 25.0 ft. "W" nail & plate.

Fd OK by Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Oct. 1967 C.S. File 54/16-25A