

PRIMARY CORNER DESCRIPTION Cor Secs 26, 27, 34 & 35

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by James P. Currin, Deputy Surveyor, under contract #438, dated May 3, 1882 - (DCSO records Vol. 6 Page(s) 2229-30)

Set a post 3 ft. long 4" sq. 20" in the ground for cor. to secs. 26, 27, 34 & 35 mkd. T23S S26 on NE, R3W S35 on SE, S34 on SW, & S27 on NW, faces with 1 notch on S and 2 notches on edges from which

- A Cedar, 8" dia., bears S.60°E., 30 lks., mkd: T23S R3W S35 BT.
- A Cedar, 33" dia., bears S.85°W., 6 lks., mkd: T23S R3W S34 BT.
- A Cedar, 36" dia., bears N.40°W., 4 lks., mkd: T23S R3W S27 BT.
- A Maple, 6" dia., bears N.20°E., 54 lks., mkd: T23S R3W S26 BT.

M. Hale - Weyerhaeuser Co. - March 1957 - C.S. File 53/107-1

Found - No evidence of 6" Maple N.20°E., 54 lks.
8" Cedar S.60°E., 30 lks., now 16", slow growing, some scribing leg.
33" Cedar S.85°W., 6 lks., still standing, face evident, scribing rotted off.
36" Cedar N.40°W., 4 lks., still standing, face evident, scribe gone.

Set - 2"x2" Yew post. (short)
24" Cedar S.5°W., 16.0 ft. "W" Nail & plate.
26" Cedar N.72½°W., 28.1 ft. "W" Nail & plate.
48" Cedar (OBT) N.50°W., 2.9 ft. "W" Nail & plate.
46" Cedar (OBT) S.63°W., 3.4 ft. "W" Nail & plate.

Bob Duncan, Weyerhaeuser Co. - Nov. 1961 - C.S. File 53/107

Corner burned through by slash fire, 1959

Found - 8" Cedar S.60°E., 30 lks., stump pushed over by cat., no scribing.
33" Cedar S.85°W., 6 lks., burned out stump (shell) "W" nail remained.
36" Cedar N.40°W., 4 lks., burned out stump (shell) no "W" nail.
No evidence of 6" Maple N.20°E., 54 lks.

Set - 3/4"x38" gal. conduit.
48" Cedar stump (shell), OBT N.3°W., 4.7 ft. "W" nail & plate.
46" Cedar stump (shell), OBT S.63°W., 3.4 ft. "W" nail & plate.

continued next page

PRIMARY CORNER DESCRIPTION Cor Secs 26, 27, 34 & 35

Alias	Description
Alias	Description
Alias	Description
Alias	Description

	24" Cedar stump S.5°W., 16.0 ft. "W" nail & plate. 26" Cedar stump N.72°W., 28.1 ft., "W" nail & plate.
	David Wellman - For: Weyerhaeuser Co. - 6/30/2003 - C.S. File 65/48-46

Found -	3/4"x38" galv. pipe - 1' above ground. 46" Cedar stump, S.63°W., 3.4 ft - burned out shell. "W" nail & tag. 48" Cedar stump N.3°W., 4.7 ft. - burned out shell. "W" nail & tag. 24" Cedar stump S.5°W., 16.0 ft. - rotten with tag, no "W" nail 26" Cedar stump, N.72½°W., 28.1 ft. - "W" nail & tag
Set -	1¾"x38" iron pipe w/2½" brass cap dated 2003 - 1' above ground level. 1¾" iron pipe set over top of 3/4" galvanized pipe. 11" Fir S.46°E. 23.5 ft. to spike set side center - scribed "T23S R3W 35S BT" 18" Fir N.81°E., 8.6 ft. to spike set side center - scribed "T23S R3W S26 BT" 15" Fir S.1°W., 30.0 ft. to spike set side center - scribed "T23S R3W S34 BT" 10" Fir N.81°W., 4.7 ft. to spike set side center - scribed "T23S R3W S27 BT"
Note -	Stream flowing south lies 15' West of corner area surrounding corner for 30' is very wet.