

TOWNSHIP 23 RANGE 03 POINT IDENTIFIER # 540100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 35; & 2, T24-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by James P. Currin, Deputy Surveyor, under Contract #438, dated May 2, 1882 - (DCSO records Vol. 5 Page(s) 2215)

-----  
Set a Post 36" long, 4" sq., 20" in the ground for ¼ sec. cor. mkd. ¼ on N. face, from which  
A Spruce 40" dia., bears North, 6 lks. mkd. ¼ S BT.  
A Hemlock 26" dia., bears South, 40 lks. mkd. ¼ S BT.

Douglas County Surveyors Office - V.R. Tracy, Deputy - Oct. 16, 1967 - C.S. File 54/16-26

-----  
At ¼ cor. of secs. 35 and 2, We find 1" alum. pipe for cor. and remains of OBTs as follows:  
Orig. 40" Spruce, North 4.0 ft., now only decayed remains of stump broke off at ground level. (D.Fir, not Spruce)  
Orig. 26" now 38" Hemlock, South 26.4 ft., now stump, blazes appear to have rotted before it healed.  
(Weyerhaeuser method BT)  
33" Hemlock stump N.64°E., 35.7 ft. with "W" nail and tag.  
2" I.P., 10 ft. high & painted orange, alongside cor. monument.  
Alum. pipe and Weyerhaeuser BT, unrecorded.