

PRIMARY CORNER DESCRIPTION SE. corner for Sec. 36 only

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO survey by James P. Currin, Deputy Surveyor, under Contract #438, dated May 2, 1882 - (DCSO records Vol. 5 Page(s) 2216)

Set a post 4½ ft. long, 4" sq., 24" in the ground for cor. to Tps. 23 and 24 S., Rs. 2 & 3 W. marked T23S S31 on NE.; R2W S6 on SE.; T24S S1 on SW.; and R3W S36 on NW. faces, with 6 notches on each edge, from which

- A Fir 26" dia., bears N.60°E., 22 lks. dist. mkd. T23S R2W S6 BT.
- A Vine Maple 6" dia., bears S.25°E., 44 lks. dist. mkd. T24S R2W S6 BT.
- A Vine Maple 6" dia., bears S.20°W., 23 lks. dist. mkd. T24S R3W S1 BT.
- A Fir 26" dia., bears N.45°W., 13 lks. dist. mkd. T23S R3W S36 BT.

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 5 Page(s) 2184-85)

(Chandler intersected the E. Bdy. T23S R3W at a point 10.75 chains North of the above described corner.) "I obliterated the marks on this post and those that referred to T23 and 24 S., R2 W."

Douglas Co. Surveyors Office - John M. Powell, and crew - April 1968 - C.S. File 54/27-220

Found - 1/2" Iron pipe, "Weyerhaeuser" method. (See C.S. File 53/107)

Orig. 26" now 42" Fir stump N.45°W., 8.6 ft., old bark scribe visible in poor condition. Also "W" nail.

40" Fir stump N.47°E., 13.7 ft. "W" nail and tag.

Set Brass cap at cor. mkd: County Surveyors Office
 (Reset I.P. alongside)

	R		R
T23S	3	<u>S 36</u>	2
T24S	W		W

1968

New BT - 60" Fir stump N.47°W., 26.1 ft. mkd. T23S R3W S36 CS BT.

Corner lies on SE. slope on top of cut bank of old cat road in logged off area.