

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 100440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 18; and 13, T23-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by - James E. Freeman Deputy Surveyor, under Contract #1, dated May, 28, 1851 (DCSO records Vol. 6 Page(s) 2330)

Set ¼ sec. post, from which
An Alder 10" dia., bears N.52½°E., 110 lks. dist.
A Fir 40" dia., bears N.50°W., 37 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; Clete Putnam - Aug. 5, 1959 - C.S. 49/42-12

Found - Orig. 40" now 50" Fir, snag, previously opened, shows good scribing "4 S"
No trace of orig. NE BT.

Set Brass cap at cor. mkd: County Surveyors Office
T 23 S
R5W ¼ S13 | S18 R4W
1959

New BTs -16" Cedar bears S.13½°E., 99.0 ft. scribed ¼ S18 CS BT.
14" R.Fir bears N.35°W., 12.0 ft. scribed ¼ S13 CS BT. Scribed high above new wire fence.
See sketch in file.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Mike Stone, Jerry Layne, crew - Oct. 1965 - C.S. File 54/16-4

Found - Brass cap at corner as recorded by Byron, pushed out of place.
Orig. 50" Fir snag still in place.
16" Cedar S.13½°E., 99.0 ft. now snag 10.0 ft. high, scribing visible.
14" D.Fir N.35°W., 12.0 ft., alive, in fence corner, face almost healed over, scribed high because of wire fence.

Reset Brass cap and marked one new BT:
9" D.Fir N.18°E., 31.9 ft. mkd. ¼ S18 CS BT.

BLM Resurvey by Dale T. Bedell, Cadastral Surveyor, under Group #1601, Surveyed June 1991/July 1992 - (DCSO records Vol. 51 Page(s) 19386)

The 1/4 sec. cor. of secs. 13 and 18, perpetuated and recorded by Byron, Deputy County Surveyor, in 1959 and further perpetuated and recorded by Tracy, Deputy County Surveyor, in 1965 monumented with an iron post, 1¼ ins. diam., firmly set, projecting 16 ins. above ground, with brass cap mkd. in 1959 (Cont. Next Page)

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 100440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 18; & S. 13, T23-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of an original bearing tree
A fir snag, 50 ins. diam., bears N. 50° W., 37 lks. dist., with scribe marks 4S visible on a previously opened blaze.
and remains of bearing trees mkd. by Byron
A cedar stump, 16 ins. diam., bears S. 13½° E., 140 lks. dist., with scribe marks 1/4 S18 CS visible on an open blaze.
A roothole, bears N. 35° W., 18 lks. dist., with a down fir alongside, 20 ins. diam., with healed blaze.
and a bearing tree mkd. by Tracy
A fir, 15 ins. diam., bears N. 22° E., 47 lks. dist., with healed blaze.
and a new bearing tree
A fir, 10 ins. diam., bears N. 82° W., 52 lks. dist., mkd. 1/4 S13 BT.
The corner is located S. 30° W., 0.18 chs. dist. from the corner of fences extending E. and S.

Fd. Ok by Douglas Co. Surveyors Office - Stephen J. Flause - John Pike - 5/15/2007 - C.S. File 67/21-38