

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Cor Secs 29, 30, 31, & 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Gordon & Gardner, Contract #52 dated Feb. 1855 (DCSO records Vol. 6 Page(s) 2285)

Set post corner of secs. 29, 30, 31, & 32 from which
A Fir, 5" dia., bears S.71°W., 16 lks.
A Fir, 4" dia., bears N.20°W., 16 lks.
A Maple, 6" dia., bears S.57°W., 28 lks.
A Fir, 10" dia., bears N.53°E., 811 lks.

BLM resurvey by James E. Jelley, Cadastral Surveyor, under Group #895 - Surveyed June/Sept. 1976 (DCSO records Vol. 41 Page(s) 16158)

Point for the cor. of secs. 29, 30, 31, & 32 at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:
T23S R4W
S 30 | S 29
S 31 | S 32
1976
from which
A Fir, 5" dia., bears N.68¼°E., 97 lks., mkd: T23S R4W S29 BT.
A Fir, 6" dia., bears S.53 3/4°E., 61 lks., mkd: T23S R4W S32 BT.
A Cedar, 5" dia., bears S.85¼°W., 39½ lks., mkd: T23S R4W S31 BT.
No other suitable trees available within limits.

Daniel A Renton, Minister-Glaeser Surveying - Garrett Finch & Crew - For: US Department of Interior, BLM - Great Expectation & Fast Lane -Task B -Feb. 17, 2023 - M178-72 A-F

Found - 3¼" BLM brass cap (properly mkd) 0.2 ft above ground in good condition from which:
20" Fir bears S.48°E., 41.9 ft to side center, with healed blaze (1976)
New - 22" Fir bears N.50°E., 6.9 ft to side center, mkd "T23S R4W S29 BT"
5/8" iron rod with 2" alum. cap bears N.45°W., 25.00 ft. mkd: T23S R4W SEC 30 25 ft RM PLS2830 2023
5/8" iron rod with 2" alum. cap bears S.45°W., 25.00 ft. mkd: T23S R4W SEC 31 25 ft RM PLS2830 2023
Set chaining nail at side center, BT signs on front and rear, and painted red band for existing BTs
Set chaining nail at side center, nail and washer stamped "PLS 2830" at base of blaze, BT signs on front and back and painted red band for new BT. _____