

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Sec Cor for 32 & 33 only, (South)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 6 Page(s) 2273)

-----  
Set post corner of secs. 4, 5, 32 and 33, from which  
A Fir 10" dia., bears N.70°E., 42 lks. dist.  
A Fir 10" dia., bears N.43°W., 38 lks. dist.  
A Fir 10" dia., bears S.86°E., 45 lks. dist.  
A Maple 6" dia., bears S.73°W., 51 lks. dist.

GLO survey by Oscar F. Thiel, Deputy Surveyor, under Contract #658 dated May 21, 1896 (DCSO records Vol. 7 Page(s) 3072)

-----  
Intersect N. bdy. of Tp., 271 lks. West of cor. of secs. 4, 5, 32 and 33, which I reestablished by setting a sandstone 6x8x12 ins., 8" in the ground mkd. with 4 notches on E. and 2 notches on W. edges and witnessed as described by the surveyor general.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy; Mike Stone, crew - Feb 1963 - C.S. File 53/9-123

-----  
Found - 65" Fir stump S.86°E., 29.7 ft., old axe marks on bark appear to be where Thiel destroyed bark scribing, on lower scar what appear to be portion of scribe mark "B" is visible.  
50" Fir stump N.70°E., 27.7 ft., no marks found.  
60" Fir stump N.43°W., 25.1 ft., one single axe mark found in wood approx. 110 years old.  
No trace of SW. BT.

I believe these trees to have been larger at time of original survey than field notes indicate and that they were bark scribed. Did not find rock set by Thiel. Appears to be in old slide area.

Set Brass cap at cor. mkd: County Surveyors Office

T23S R4W S 32 | S 33  
T24S R4W S 4

1963

New BTs- 52" D. Fir N.75°W., 65.0 ft. mkd. T23S R4W S32 CSBT  
12" Red Cedar S.73°E., 38.0 ft. mkd. T23S R4W S32 CS  
BT.

No trees available to NE.  
Corner lies on very steep N. face.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec Cor for 32 & 33 only, (South)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #895, surveyed 1976 - (DCSO records Vol. 41 Page(s) 16134)

-----

The Sec. Cor., perpetuated and recorded by Godfrey in 1963, monumented with an iron post, 1¼" dia., firmly set, projecting 2" above ground, with brass cap mkd. in 1963, from which the remains of the original bearing trees:

A sawed Fir stump 48" dia., bears N.70°E., 42 lks. dist., no marks visible.

A sawed Fir stump 42" dia., bears S.86°E., 45 lks. dist., no marks visible.

A sawed Fir stump 48" dia., bears N.43°W., 38 lks. dist., with chaining notch visible on decayed blaze.

and the remains of bearing trees mkd. by Godfrey:

A sawed Cedar stump 20" dia., bears S.75°E., 56½ lks. dist., with healed blaze.

A Fir 54" dia., bears N.75 3/4°W., 99 lks. dist., with healed blaze.

and a new bearing tree:

A Maple 15" dia., bears N.77°E., 155 lks. dist. mkd. T23S R4W S33 BT.

Fd. and used in BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #979, surveyed May/Sept. 1979 - (DCSO records Vol. 42 Page(s) 16379)

Fd. OK, Sept. 1994 by D. Baker - M 119-40  
Fd. Ok by D. Edwards 3/2007 - M152-55

BLM Dependent resurvey by A. Bert Skeesick, Cadastral Surveyor and Robert H. Browning, Survey Tech, under special instructions and Group No. 2210, surveyed Oct./Nov. 2008 - (DCSO records Vol. 57 Page(s) 22353)

-----

The cor. of secs. 32 & 33 only, on the S. bdy. of the Tp., monumented with an iron post, 1¼" dia., firmly set, projecting 2" above the ground, with brass cap (properly) mkd from which the remains of the original bearing trees

A sawed fir stump, 36" dia., bears N.70°E., 27.7 ft., with no marks visible.

A sawed fir stump, 44" dia., bears S.86°E., 29.7 ft., with no marks visible.

A sawed fir stump, 48" dia., bears N.43°W., 25.1 ft., with no marks visible.

and the remains of BTs mkd. by Godfrey, in 1963, reported by Jelley in 1979

continued next page

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Sec Cor for 32 & 33 only, (South)

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

A sawed cedar stump, 17" dia., bears S.75°E., 37.3 ft., with no marks visible.  
A fir, 60" dia., bears N.75¼°W., 65.3 ft., with a healed blaze.  
and a bearing tree mkd. by Jelley in 1976  
A maple, 28" dia., bears N.77°E., 102.3 ft., with a healed blaze.

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor and Robert H Browning, Survey Tech, Under Group No. 2168, Surveyed May/Nov. 2007 - DCSO records Vol. 57 Page(s) 22587-8  
-----  
The cor. of secs. 32 & 33 only on the S bdy. of the Tp, monumented with an iron post, 1¼" dia., firmly set, projecting 2" above ground, with brass cap (properly) mkd. from which the remains of the orig. bearing trees  
A sawed fir stump, 44" dia., bears N.70°E., 27.7 ft., with no marks visible.  
A sawed fir stump, 55" dia., bears S.86°E., 29.7 ft., with no marks visible.  
A sawed fir stump, 48" dia., bears N.43°W., 25.1 ft., with no marks visible.  
and the remains of BTs mkd. by Godfrey, in 1963  
A cedar snag, 19" dia., bears S.75°E., 37.3 ft., with no marks visible.  
A fir, 52" dia., bears N.75¼°W., 65.3 ft., with a healed double blaze.  
and bearing tree mkd. by Jelley in 1976  
A maple, 26" dia., bears N.77°E., 102.3 ft., with a healed blaze.