

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4 & 5; and 32 & 33, T22-4

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by - James E. Freeman Deputy Surveyor, under Contract #1, dated May, 28, 1851 (DCSO records Vol. 6 Page(s) 2267 and 2270)

Set post cor. of secs. 4, 5, 32 and 33, from which
A Fir 40" dia., bears S.20°E., 46 lks. dist.
A Fir 16" dia., bears S.30°W., 78 lks. dist.
A Fir 18" dia., bears N.10°W., 77 lks. dist.
A Fir 16" dia., bears N.54°E., 18 lks. dist.

Corner report by Glen McChesney - For: Weyerhaeuser Co. - Nov. 11, 1959 - C.S. File 53/105-25

GLO post, no trace.
Set 1" alum. pipe by distance from NW and SW. original BTs.
Found - 16" Fir, N.54°E., 18 lks., now 24" blowdown stump, badly burned, out of place, bears N.38°E., 12.8 ft.
40" Fir, S.20°E., 46 lks., now large burned and rotted Fir stump, bears S.18°E., 26.5 ft.
16" Fir S.30°W., 78 lks., now 28" Fir stump, old axe marks, bears S.32°W., 51.5 ft.
18" Fir, N.10°W., 77 lks., now 32" Fir stump, chopped out lower face and found scribed "BT", bears N.11°W., 50.8 ft.
Accessories Added:
3" Fir N.52°E., 40.4 ft. with "W" nail and plate.
6" Fir S.80°E., 25.0 ft. with "W" nail and plate.
28" Fir stump S.32°W., 49.5 ft. with "W" nail and plate. (Orig. BT)
14" W.Oak N.12°W., 15.6 ft. with "W" nail and plate.

Douglas Co. Surveyors Office - Wm. S. Stoffel and Mike Stone, crew - Jan. 1965 - C.S. File 53/101-47

Found - 1" alum. pipe at corner, not recorded. (See above record)
40" Fir S.20°E., 30.4 ft., now burned stump.
16" Fir S.30°W., 51.5 ft., now stump, good scar.
18" Fir N.10°W., 50.8 ft., open, shows scribing "BT"
16" Fir N.54°E., 11.9 ft., not found.
New BTs -9" Fir S.80°E., 25.0 ft. scribed T23S R4W S4 CS BT.
8" Fir N.52°E., 40.4 ft. mkd. T22S R4W S32 CS BT.
19" B.Oak N.12°W., 15.6 ft. mkd. T22S R4W S32 CS BT.
Fence N. & S., 4.4 ft. West.

FD OK by Les Roberts, July 1996 - M 125-48
Fd. Ok April 1998, by K. Hoffine - M 128-60