

PRIMARY CORNER DESCRIPTION Center 1/4 Sec. 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

James A. Branch - For: U.S. National Bank - Sept. 1990 - M 110-58 & C.S. File 63/104  
-----

CORNER REPORT ONLY  
 Found - Steel fence post (no record)  
           20" (11") Fir, bears N.83°E., 8.3 ft. (Not of rec. in DCSO)  
           9" Fir, bears S.61°W., 8.2 ft. tree is now standing but is dead. (Not of record in DCSO)

---

Daniel Baker - For Weyerhaeuser Co. - Sept. 1994 - M119-38  
-----

Set - 2" x 32" iron pipe with 2½" Brass cap marked: "T23S R4W C¼ S33 PLS 1978 1994"  
       18" Fir, N.87°E., 7.0 ft. to "W" nail -scribed "C¼ S33 BT"  
       25" Fir, S.14°E., 29.0 ft. to "W" nail -scribed "C¼ S33 BT"  
       18" Fir, S.83½°W., 12.6 ft. to "W" nail -scribed "C¼ S33 BT"  
       18" Fir, N.19°W., 22.0 ft. to "W" nail -scribed "C¼ S33 BT"

Found - Metal fence post bears S.73¼°E., 3.8 ft. from set corner. Record: 1977 BLM Administrative survey center ¼ monument.  
 BTs to metal fence post:  
       Record: 20" Fir, N.83°E., 8.3 ft. - 1977 BLM  
       Record: 9" Fir, S.61°W., 8.2 ft. - 1977 BLM now dead

---

Fd. OK by D. Baker, Nov. 1999 - M132-20

---

BLM Dependent resurvey by Timothy J. Moore, Cadastral Surveyor & Robert Browning, Surveying Technician under Group #1955, surveyed 2000/2001 (DCSO rec. Vol. 54 pg(s) 20890-1)  
-----

The center ¼ sec. cor. of sec. 33, established by Baker, in 1994, and is accepted as the cor., monumented with an iron pipe, 2" dia., firmly set, projecting 2" above the ground and a brass cap, 2½" dia., cemented to top of iron pipe, with brass cap (properly) mkd.  
 from which the remains of bearing trees mkd. by Baker  
   A fir, 19" dia., bears N.89°E., 7.6 ft., with a healed double blaze.  
   A fir, 26" dia., bears S.17½°E., 31.0 ft., with a healed double blaze.  
   A fir, 18" dia., bears S.79¾°W., 13.6 ft., with a healed double blaze.

continued next page

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 340140

PRIMARY CORNER DESCRIPTION Center 1/4 Sec. 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A sawed fir stump, 19" dia., bears N. 19¼° W., 21.1 ft., with a healed double blaze.

From this point, a point unofficially established as the center ¼ sec. cor. of sec. 33, during an administrative survey by the BLM, in 1977, bears S.29°20'25"W., 1.24 ft., monumented with fence post, inverted, projecting 40" above the ground, from which the remains of a bearing tree reported during the administrative survey.

A fir snag, 7" dia., bears S.62°W., 8.5 ft., with no marks visible on open blaze.

This point was not utilized during the course of this survey,

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor and Robert H Browning, Survey Tech, Under Group No. 2168, Surveyed May/Nov. 2007 - DCSO records Vol. 57 Page(s) 22600

-----  
The ¼ sec. cor. of secs. 32 and 33, monumented with an iron post, 2½" dia., firmly set, projecting 1" above ground, with brass cap (properly) mkd.

from which bearing trees mkd. by Jelley in 1976

A fir, 20" dia., bears N.28½°E., 10.6 ft., with a healed blaze.

A fir, 14" dia., bears N.73¼°W., 15.0 ft., with a healed blaze.

Corner is located 6.5 ft. W. of a woven wire fence, extends N. and S.