

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 33 & 34

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Gordon & Gardner, Contract #52 dated Feb. 1855 (DCSO records Vol. 6 Page(s) 2277)

Set ¼ Sec. post from which
 A Cedar, 18" dia., bears S.74°W., 33 lks.
 A Cedar, 20" dia., bears S.63°E., 38 lks.

Wilford N. Haines - For: Dave Rust - July 1960 - M 19-38

Found - 20" Cedar, now a rotted stump, S.63°E., 38 lks.
Set - 1" x 1" T-iron in East edge of road.
 5" W.Fir S.40½°E., 79.5 ft.
 7" R.Cedar, N.72½°W., 126.6 ft.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Mike Stone - Jerry Layne - Nov. 1965 - C.S. File 54/16-36

Found - BTs as recorded by Haines
 Haines' "T" iron pushed out & Cedar stump used for orig. also gone.
Set - Brass cap at cor. mkd: COUNTY SURVEYORS OFFICE 1965
 T23S R4W ¼ S33|S34
 5" now 7" W.Fir S.40½°E., 79.5 ft., healed blaze. Do not open.
 7" now 11" R.Cedar N.72½°W., 126.0 ft., scribe visible on partially healed blaze.
Note - This corner lies on east edge of road, course N & S curving to southwest.

BLM resurvey by James E. Jelley, Cadastral Surveyor, under Group #895 - Surveyed June/Sept. 1976 (DCSO records Vol. 41 Page(s) 16145)

The ¼ cor. perpetuated and recorded by Haines in 1960 and further perpetuated and recorded by Tracy in 1965, from orig. evidence no longer in existence, monumented with an iron post, 1¼" dia., firmly set, with brass cap top 2" below surface of graveled driveway, 15 lks. wide, bears N & S, turning SW. The brass cap is properly mkd. from which the BTs mkd. by Tracy
 A Grand Fir, 10" dia., bears S.41°E., 120½ lks., with healed blaze.
 A Cedar, 15" dia. bears N.73½°W., 193 lks., w/healed blaze
I add a reference monument
 An Iron post, 28" long, 2½ dia, set 24" in the ground, for a ref. mon., bears S.34°E., 28 lks., w/brass cap mkd. ¼ S34 RM 1976, & an arrow pointing to the corner.

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 33 & 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - Larry E. Monrean - Karen Reed
- Frank C. Silagy - Sept. 13, 1979 - C.S. File 61/6-56

Found - A 1" x 36" I.P. with brass cap marked "County
Surveyors Office T23S ¼ S33 S34 R4W 1965. Cap is
located below ground surface.
A buried BLM brass cap bearing S.45°W., approx. 3
ft. marked "¼" S33 S34 T23S R4W 1976.
Haines "T" iron (1960) not found.
A 7" Cedar now 18" bears N.73½°W., 126.4 ft. (Rec.
N.72½°W., 126.6 ft.) with well healed blaze.
A 5" now 10" Fir, bears S.41°E., 79.5 ft. (Rec.
S.40½°E.) with rotted blaze 2 ft. high & well
healed blazes above and below rotted blaze.

Note 1 - These bearings and distances measured from county
cap. Corner lies in East edge of road course N-S
curving to SW.

Note 2 - BLM office to remove BLM cap.

Douglas Co. Surveyors Office - Stephen J. Flause - Karen
Mosely - Debby Prado - Dawna Atterbury - Jan. 10, 1980 - C.S.
File 61/6

Found - A filled in hole with scraps of flagging at S.35°W.,
approx. 3 ft. distant. We find NO BLM cap.
Find accessories as noted above.
New BTs- A 24" D.Fir, bears N.6½°E., 113.5 ft., with a double
blaze mkd: ¼ S34 CS BT.
A 16" D.Fir, bears S.75°W., 142.9 ft., with a double
blazed mkd: ¼ S33 CS BT.

Fd. DCSO brass cap, 9/1990 - M 110-58
Fd. Ok by Dan Baker - 9/1994 - M 119-38
Fd. OK - 1/1995 - M 121-69

Dan Baker - For: Rocking "C" Ranch - 11/1999 - M 132-20

Found - DCSO cap dated 1965
12" Grand Fir, S.41°E., 79.5 ft. - closed face, (rec
S.40½°E., 79.5 ft.) 1965 DCSO
21" Cedar, N.73°W., 127.4 ft. - closed face, (rec.
N.72½°W., 126.0 ft.) - 1965 DCSO
1976 BLM brass cap RM S.34 3/4°E., 18.6 ft. (rec.
S.34°E., 28 lks.) - 1976 BLM
Set - 8" Cedar, S.16°E., 36.8 ft.

continued next page

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 400140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 33 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Fd, & used on BLM Dependent resurvey by Timothy J. Moore, Cadastral Surveyor & Robert Browning, Surveying Technician under Group #1955, surveyed 2000/2001 (DCSO rec. Vol. 54 pg(s) 20892-3)